

## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10071/MR Lee Si Yang, Samuel
	Reg No/Reg Date	SML8504T*KC17/ 07/06/201
	Date In/Mileage	03/04/2021/ 0
	Chassis No	KNAF3416MK5044995
	Engine No	G4FGKH737946
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/04/2021/ 12:49	QUK	282 / Kevin Leong	31467			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT RH DOOR								3600.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & FRT RH DOOR								1750.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								120.00
M SUNDRY TO TOP UP AIRCON GAS								80.00
M SUNDRY PERFORM RUST PREVENTION								120.00
A 33900099 REPLACE FRT UNDERCARRIAGE								400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING								30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY TO APPLY ZERTONA COATING								400.00
M SUNDRY SUNDRIES								50.00
M	LAMP ASSY-HEAD,LH				1.00	2210.00	20.00	1768.00
M	HORN ASSY-LOW PITCH				1.00	74.00	20.00	59.20
M	PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M	HINGE ASSY-HOOD,RH				1.00	43.00	20.00	34.40
M	HINGE ASSY-HOOD,LH				1.00	43.00	20.00	34.40
M	PANEL-FENDER,LH				1.00	430.00	20.00	344.00
M	INSULATOR-FENDER LH				1.00	27.00	20.00	21.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV10071/MR Lee Si Yang, Samuel
	Reg No/Reg Date	SML8504T*KC17/ 07/06/201
	Date In/Mileage	03/04/2021/ 0
	Chassis No	KNAF3416MK5044995
	Engine No	G4FGKH737946
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	05/04/2021/ 12:49	QUK	282 / Kevin Leong	31467		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	CARRIER ASSY-FRONT END MODULE			1.00	675.00	20.00	540.00
M	ARM COMPLETE-FR LWR,LH			1.00	286.00	20.00	228.80
M	KNUCKLE-FRONT AXLE,LH			1.00	350.00	20.00	280.00
M	HUB ASSY-FR WHEEL			1.00	436.00	20.00	348.80
M	GEAR ASSY-STEERING			1.00	770.00	20.00	616.00
M	STRUT ASSY-FR,LH			1.00	280.00	20.00	224.00
M	PAD-FRONT SPRING,UPR			1.00	11.00	20.00	8.80
M	PAD-FRONT SPRING,LWR			1.00	23.00	20.00	18.40
M	INSULATOR ASSY-STRUT			1.00	85.00	20.00	68.00
M	BRACKET-FR BUMPER UPR SIDE MTG			1.00	22.00	20.00	17.60
M	AIR DUCT-FR BUMPER,LH			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY			1.00	84.00	20.00	67.20
M	LAMP ASSY-SIDE REPEATER,LH			1.00	143.00	20.00	114.40
M	COVER-FR BUMPER			1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER			1.00	485.00	20.00	388.00
M	MOULDING-FRONT BUMPER,LH			1.00	216.00	20.00	172.80
M	GUARD ASSY-FRONT WHEEL,LH			1.00	95.00	20.00	76.00
M	ORNAMENT-KIA NO.115			1.00	32.00	20.00	25.60
M	WHEEL ASSY-ALUMINIUM			1.00	926.00	20.00	740.80

Confirm & accepted by

<b>Nett</b>	<b>14,736.00</b>
<b>7% GST on</b>	<b>14736.00</b>
<b>Total Payable</b>	<b>15,767.52</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.