

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 05 Apr 2021)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2268X/05/04/2021 10:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,106.00 FL de
2	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL Ry
3	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL net
4	1		*REVERSE SENSOR	20.00	0.00	*135.70 FL R.N.

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,491.70
- List Item Discount on L Items (S\$)	298.34

Total Parts (S\$)	1,193.36
--------------------------	-----------------

ComfortDelGro Engineering Pte Ltd/SHC2268X/05/04/2021 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1128

962.40

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280 300.00
2	SPRAY PAINTING	New	250 300.00
3	R/I REVERSE SENSOR	New	30 120.00
Gross Labour Cost (S\$)			560 720.00

ComfortDelGro Engineering Pte Ltd/SHC2268X/05/04/2021 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tuffin 9745749
 'up'
 - 'up' 01/4/21 @ 330
 02 days
 US Repair after repair.

1473.40
 1154/1200
 02 days
 #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: