


VEHICLE DETAIL



Vehicle No	QX 1293 L	SCDF Ref. No.	ACC-IND-21-08
Date Booked In			

REPAIR DESCRIPTIONS

- 1) Remove & replace bonnet sticker & wording (pic 1,2)
- 2) Panel beat dented bonnet (pic 1,2)
- 3) Putty & spray paint bonnet (pic 1,2)
- 4) Spray lacquer over after putting up sticker & wording for bonnet (pic 1,2)
- 5) Remove & replace front bumper retainer (pic 3)
- 6) Remove & replace front dented bumper (pic 3)
- 7) Remove & replace dented AP panel (pic 4,5)
- 8) Remove & replace dented radiator grill (pic 6)
- 9) Remove & replace R/H fender sticker (pic 7)
- 10) Panel beat dented R/H fender (pic 7)
- 11) Remove & replace front dented number plate (pic 8)
- 12) Panel beat dented siren speaker bracket (pic 9)
- 13) Remove & replace dislodged siren speaker (pic 10)
- 14) Remove & replace dented power steering pipe (pic 11)
- 15) Remove & replace air con motor fan (pic 12)
- 16) Remove & replace air con condenser (pic 13)
- 17) Remove & replace radiator (pic 14)
- 18) Remove & replace radiator top & bottom hose (pic 14)
- 19) Putty & spray paint AP panel & R/H fender (pic 4,5&7)

PHOTOS OF DAMAGED PARTS

Bonner dented (pic 1)	Bonnet dented (pic 2)
	
Front bumper dented (pic 3)	AP panel dented (pic 4)
	
AP panel dented (pic 5)	Radiator grill dented (pic 6)

 AP panel dented	 Radiator grill dented
R/H fender dented (pic 7)	Front number plate dented (pic 8)
 R/H fender dented	 Front number plate dented
Siren speaker bracket dented (pic 9)	Siren speaker dislodged (pic 10)
 Siren speaker bracket dented	 Siren speaker dislodged
Power steering pipe dented (pic 11)	Air con motor fan crack (pic 12)
 Power steering pipe dented	 Air con fan crack
Air con condenser dented (pic 13)	Radiator leak (pic 14)
 Air con condenser dented	 Radiator leak
QX 1293 L	
	