

REF:

CC4/ALG 21004290/Dr3

REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 7/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG 7577C Yr Regn: 2016, OctType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Suzuki Vitara C.C. 1586Colour: Seige A/C: Insured / Std / NI / NASp. Reading: 65591 T/Radio: Insured / Std / NI / NAEng/No: M16A2081091C/No: TSM LYD21S00268893Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 215/55 R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 02/04/2021 D.O.I. 06/04/2021Survey held at Alfred Auto AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ALG SML 8504 TRepair on 7/P as no used parts in market due to rare model.30/04/2021 Invoice 7/P 9914.30 with 7 days 7 reg

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.E. A/C _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Workshop (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 30421

Date: 03.4.2021

Phua Li Choo

Blk 332 #11-253 Serangoon Ave 3

Singapore 550332.

Suzuki Vitara

Estimate Repair Cost for Vehicle Reg. No: SLG 7577 C

✓ 1 Pc. Front Bonnet	✓	1,020.00	✓
1 Pc. Front Bonnet Sponge	✓	498.00	✓
10 Pcs. Front Bonnet Sponge Clips	✓	60.00	✓ 15/- SW
2 Pcs. Front Bonnet Hinger	✓	296.00	X
1 Pc. Front Fog Lamp	✓	499.80	✓
RH 1 Pc. Front Fog Lamp Holder	✓	186.50	✓
1 Pc. Wiper Tank Assy.	✓	508.00	✓ 125.30
RH 1 Pc. Head Lamp	✓	2,499.05	✓ 2499.05
1 Pc. Head Lamp Module	✓	989.00	X
RH 1 Pcs. Head Lamp Bracket	✓	56.00	✓
1 Pc. Front Grille Assy.	✓	468.40	X
1 Pc. Front Grille Logo	✓	332.50	X
10 Pcs. Front Grille Clips	✓	60.00	X
1 Pc. Front Bumper	✓	998.80	✓ 998.80
1 Pc. Front Bumper Grille (CTR)	✓	189.20	X
1 Pc. Front Bumper Towing Cover	✓	26.00	✓
1 Pc. Front Bumper Lamp LED	✓	869.80	✓ 869.80
1 Pc. Front Bumper Corner Pad	✓	320.00	✓
1 Pc. Front Bumper Centre	✓	330.00	X
1 Pc. Front Bumper Lower	✓	180.90	X
12 Pcs. Front Bumper Clips	✓	72.00	✓ 30/- SW
1 Pc. Front Bumper Side Catch	✓	28.80	X
1 Pc. Front Bumper Retainer	✓	29.30	✓
1 Pc. Front Bumper Reinforcement	✓	729.85	✓ 729.85
1 Pc. Front RH Fender	✓	325.50	✓
1 Pc. Front RH Fender Garnish	✓	110.60	✓
10 Pcs. Front RH Fender Garnish Clips	✓	60.00	✓ 15/- SW
1 Pc. Front RH Fender Dust Cover	✓	127.50	✓
10 Pcs. Front RH Dust Cover Clips	✓	60.00	✓ 15/- SW
2 Pcs. Distance Sensor	✓	252.00	✓
1 Pc. Distance Harnes Wire	✓	288.00	X
1 Pc. Support Panel	✓	910.00	X
1 Pc Fender Top Garnish	✓	199.00	✓

Page 1 of 2

List 9072.00
10% 8169.30

SW 75.00



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



1 Pc. Coolant *HN*

90.00 *X*

Total (Panels / Parts): 13,471.50 (SGD)

LABOR CHARGES

To remove & refit wiring, checking & memory to standard Setting & refocus head lamp. *120.00 30/-*

To repair, knocking, straightening all accident affected area. *900.00 800/-*

To respray painting on all accident damage affected area. *1,200.00 800/-*

To rust proof all accident affected area. *120.00 40/-* *1670.00*

To remove & refit radiator, fan motor assy & all affected Area. *180.00 HN*

To remove & refit air-con condenser, pipe & top-up gas & oil. *280.00 HN*

Total (Labor Charges): 2,800.00 (SGD)

P/P 9914.30

TOTAL COST SUMMARY

PANELS / PARTS 13,471.50
LABOR CHARGES 2,800.00

Grand Total: 16,271.50 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Alfred Quah

ALFRED AUTO SERVICES & SUPPLIES

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Page 2 of 2

Dismantle on 12/04/2021

*06/04/2021 @ 1000hrs
Not Andrew
Part by Part.*

*Photo after repair
with damaged parts.*

*you
LKK Auto*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: