

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAN GUAT KWEE
332 TAMPINES ST 32 #07-546
SINGAPORE 520332

ATTN:

Your Ref No: TP 0321-6312
Claim Type: Third Party
Accident Date: 29/03/2021
TP Veh Reg No: SJC 1636 A

TP 1st Cap

Jus.

Estimate No: EST1506821
Date: 30 Mar 2021
Policy No: PNPV2020-00009126
Veh Reg No: SMF1129X
Make/Model: BMW 420i
Chassis No: WBA4H32090BP27616
Engine No: F9583084B48B20A
Reg. Date: 25/09/2018

Estimate Repair Cost to Vehicle No :SMF1129X

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 FRONT BUMPER <i>behind.</i>	1,313.150	1 PC	1,313.15	✓
2 FRONT BUMPER SIDE HOLDER - RH/LH <i>new</i>	38.1500	2 PC	76.30	✗
3 FRONT BUMPER CLIPS <i>new</i>	3.0000	10 PC	30.00	✓
			1,419.45	
		Less 5%	70.97	1,348.48
Labour				
4 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	350.0000	1 JOB	350.00 <i>200</i>	
5 TO RESPRAY PAINT ON ACCIDENT PORTIONS <i>480</i>	400.0000	1 JOB	400.00 <i>250</i>	
6 TO CHECK WIRING	50.0000	1 JOB	50.00 <i>30</i>	
			800.00	800.00
Total			S\$ 2,148.48	
Add GST @ 7%			150.39	
Total Amount Payable			S\$ 2,298.87	

TOTAL: SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED NINETY EIGHT AND CENTS EIGHTY SEVEN ONLY

For Progressive Car Care Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE

[Signature]

Adrian Lj
15/04/21 P/P.

02 Days.
Total: 1755.99
(P/P)