

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E
8 Kaki Bukit Avenue 4
#08-09 Premier @ Kaki Bukit
Singapore 415875
Tel: 6341 6789 Fax: 6341 6778
Email: smartoneauto@gmail.com

LKK Auto Consultants hence notify the Repairs of the following:

SMART ONE AUTO PTE LTD

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairs: **DATE: 05.04.21**
Signature: _____
Date: _____

TO : **INDIA MOTOR CLAIMS DEPTS**
VEHICLE NO : **GBJ6296Y**
MODEL : **TOYOTA DYNA**
DATE OF ACCIDENT : 04.04.21
TIME OF ACCIDENT : 11:45HRS

KDY2318038173

Jasper.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented.</i>	1	\$ 1,370.00	\$ 1,370.00
2	TAILGATE HINGE <i>Dented. 2 pieces.</i>	4	\$ 165.00	\$ 660.00
3	TAILGATE SIDE LOCK LH <i>new</i>	1	\$ 125.00	\$ 125.00
4	TAILGATE STOPPER RUBBER LH <i>3pc</i>	1	\$ 35.00	\$ 35.00
5	TAILGATE STOPPER BRACKET LH <i>new</i>	1	\$ 175.00	\$ 175.00
6	SIDE GATE SAFETY LOCK LH <i>new</i>	1	\$ 132.10	\$ 132.10
7	REAR NUMBER PLATE HOLDER <i>Best</i>	1	\$ 184.00	\$ 184.00
8	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 45.00	\$ 90.00
9	TAIL LAMP <i>crackd.</i>	2	\$ 245.00	\$ 490.00
10	TAIL LAMP LOWER REFLECTOR <i>crackd</i>	2	\$ 55.20	\$ 110.40
11	TAIL LAMP SUPPORT BRACKET <i>Best</i>	2	\$ 97.00	\$ 194.00
12	REAR STICKER 'DYNA' <i>new</i>	1	\$ 45.00	\$ 45.00
13	REAR END PENEL <i>Dented.</i>	1	\$ 1,245.00	\$ 1,245.00
14	REAR END PANEL REFLECTOR <i>crackd</i>	2	\$ 69.80	\$ 139.60
15	REAR TOOLS BOX <i>Dented</i>	1	\$ 467.40	\$ 467.40
16	REAR TOOLS BOX BRACKET <i>Best</i>	1	\$ 198.70	\$ 198.70
17	REAR END CROSS MEMBER <i>Dented</i>	1	\$ 2,280.00	\$ 2,280.00
18	REAR 2ND END CROSS MEMBER <i>Repair</i>	1	\$ 2,467.00	\$ 2,467.00
19	SPARE TYRE CHAIN BOX <i>crackd</i>	1	\$ 398.00	\$ 398.00
20	REAR EXHAUST <i>Best.</i>	1	\$ 790.00	\$ 790.00
21	REAR EXHAUST MOUNTING <i>torn. 1 piece</i>	2	\$ 68.00	\$ 136.00
22	REAR EXHAUST HOLDER <i>new</i>	1	\$ 170.00	\$ 170.00

5516.10
4137.07

TOTAL PRICE \$ 11,902.20
LESS 25% \$ 2,975.55
SUB TOTAL PRICE \$ 8,926.65

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00

TO : INDIA MOTOR CLAIMS DEPTS
 VEHICLE NO : GBJ6296Y
 MODEL : TOYOTA DYNA
 DATE OF ACCIDENT : 04.04.21
 TIME OF ACCIDENT : 11:45HRS

2	TAIL GATE COMPANY STICKER <i>new</i>	1	\$ 400.00	\$ 400.00	<i>180.</i>
3	TAIL GATE 'AR' STICKER <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
4	TAIL GATE '70KM/H' STICKER <i>3x1</i>	1	\$ 40.00	\$ 40.00	<i>15</i>
5	TAIL GATE '13PAX' STICKER	1	\$ 40.00	\$ 40.00	<i>15</i>
6	TAILGATE ALUMINIUM COVER (SPECIAL TYPE) <i>new</i>	1	\$ 680.00	\$ 680.00	<i>400.</i>
7	TAILGATE STICKER (1550KG) <i>new</i>	1	\$ 350.00	\$ 350.00	<i>40.</i>
8	REAR END PANEL SEALANT <i>new</i>	1	\$ 180.00	\$ 180.00	<i>60</i>
9	REAR END PANEL STICKER (BLACK) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>20.</i>
10	REAR FLOOR ALUMINIUM COVER (SPECIAL TYPE)	1	\$ 2,800.00	\$ 2,800.00	<i>+</i>
11	REAR STEP BAR (SPECIAL TYPE) <i>Best.</i>	1	\$ 350.00	\$ 350.00	<i>150</i>
12	REAR SPARE TYRE (BIG) <i>3x1</i>	1	\$ 480.00	\$ 480.00	<i>+</i>
13	REAR SPARE TYRE RIM (BIG) <i>new</i>	1	\$ 250.00	\$ 250.00	<i>+</i>

930

TOTAL \$ 5,790.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,800.00	<i>800.</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	<i>550.</i>
3	REMOVE AND REFIX REAR FLOOR AND TAILGATE COVER ALUMINIUM	\$ 650.00	<i>+</i>
4	REAR CHASSIS ALIGHMENT	\$ 250.00	<i>+</i>
5	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>80</i>
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>+</i>

1430

TOTAL \$ 4,660.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,716.65
 TOTAL LABOUR COST : \$ 4,660.00
 TOTAL REPAIR COST : \$ 19,376.65

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

Admin Lg
h/s 05/04/21
06 Days.
total: 6497.07
h/s: 5.2K
(5.2K)