

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

5-Apr-21

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1723 A

1 pc	Rear bumper	\$	459.40 <i>Ry</i>
1 pc	Rear bumper reinforcement	\$	294.80 <i>X</i>
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00	\$	30.00 <i>X</i>
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00 <i>X</i>
2 pcs	Rear bumper n/s & o/s stay @ \$138.10	\$	276.20 <i>Y</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10	\$	66.20 <i>X</i>
1 pc	Rear bumper lower moulding centre	\$	47.50 <i>Ry</i>
1 pc	Rear bumper lower cover	\$	216.50 <i>de</i>
1 pc	Rear bumper cap hook	\$	9.10 <i>X/Ry</i>
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80 <i>X/Ry</i>
		\$	1,478.50 <i>216.50</i>
		\$	295.70
		\$	1,182.80 <i>173.20</i>
		Less 20%	
		\$	48.00 <i>X</i>
		\$	280.00 <i>X</i>
		\$	50.00 <i>X</i>
		\$	50.00 <i>20</i>
		\$	120.00 <i>X nn</i>
		\$	180.00 <i>X nn</i>
		\$	650.00 <i>200</i>
		\$	600.00 <i>200</i>
		\$	120.00 <i>X nn</i>
		\$	3,280.80 <i>420</i>

### S/N

- 1 set Rear bumper clips
- 1 set Reverse sensor
- 1 pc Rear number plate with casing

### Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc

To putty and spray painting on rear bumper, end panel, Rear bumper lower cover (Black)

To apply rustproofing on the repaired and replaced panels.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *No sensor*

Date: *No sensor*

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*WP - Tanpin 97495749*  
*5/4/21 2:30 pm*  
*Resurvey before paint.*  
*02 days*  
*tanpin@shanda.com*

*17320*  
*420*  
*593.20*  
*02 days*