



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103402

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/05/2021
Reference CC4/FCI21004301/Qes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. CB 8803B
Insured Veh. SBS 3320H
Claim No. D21001043MFBP/1
Policy No. D-20096309MFBP
Accident Date 29/03/2021
Inspection Date 06/04/2021

Description	Total
Survey Inspection	236.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	236.00
GST (7%)	16.52
Grand Total	252.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21004301/Qes3q2 Date: 14/05/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 3320H	Veh. Inspected	CB 8803B
	Policy No.	D-20096309MFBP	Coverage (\$)	0.00
	Claim No.	D21001043MFBP/1	Excess (\$)	0.00
	Assign From	JACLYN	Assign Date	05/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	YUTONG ZK6107H	c.c	6690
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	LZYTBD6XE1024349	Colour	GREEN
	Odometer	357616 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	PIRELLI	6 mm
	L/H Front Tyre	295/80 R22.5	PIRELLI	6 mm
	R/H Rear Tyre	295/80 R22.5	PIRELLI	6 mm
	L/H Rear Tyre	295/80 R22.5	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/03/2021	Inspection Date	06/04/2021
	Survey held at	A T AUTO CONSULTANT 113 TECK WHYE LANE, #05-650, SINGAPORE 680113		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 8803B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	CRUMPLED		
	FRONT AUTO SIDE MIRROR WITH WARMER L/H (SN)		1,860.00	1,660.00
			1,860.00	1,660.00
	<u>LABOUR</u>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.		300.00	250.00
	SPRAY PAINTING ON AFFECTED AREA.		300.00	250.00
	WIRING CHARGES & TESTING COMMISSIONING .		100.00	30.00
	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS.		100.00	50.00
	TRANSFER SIDE MIRROR MECHANISM L/H .		100.00	30.00
			900.00	610.00
GRAND TOTAL			2,760.00	2,270.00
RECOMMENDED COST OF REPAIRS				2,270.00

Report Ref No. CC4/FCI21004301/Qes3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 8803B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. CB 8803B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

