

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKW 6586K
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 03/04/2021

TP Veh Reg No: SLN8341Y

Not Notified

11 Day &

Money After Repair

Estimate No: ES2190314/YISHUN

Date: 05 Apr 2021

Policy No: 5118262173

Veh Reg No: SKW6586K

Make/Model: HYUNDAI HYUNDAI
TL TUCSON 2.0 GLS AT

Chassis No: KMHJ3813MGU071470

Engine No: G4NAFU075631

Reg. Date: 11/11/2015

Estimate Repair Cost to Vehicle No :SKW6586K

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER UPPER	494.70	1 PC	CM 494.70	✓
2 FRONT BUMPER LOWER	381.40	1 PC	SM 381.40	X
3 FRONT BUMPER REINFORCEMENT	603.60	1 PC	603.60	?
4 FRONT BUMPER SPONGE	94.00	1 PC	94.00	?
5 FRONT BUMPER RH SIDE RETAINER	9.90	1 PC	DIY 9.90	✓
6 FRONT BUMPER CLIPS	3.50	6 PCS	SM 21.00	✓
7 FRONT GRILLE	953.70	1 PC	CM 953.70	✓
8 FRONT GRILLE CLIPS	3.50	6 PCS	SM 21.00	✓
9 HORNS	95.90	2 PCS	SM 191.80	?
10 BONNET	1,617.80	1 PC	R 1,617.80	✓
11 BONNET INNER LOCK	142.40	1 PC	142.40	?
12 BONNET INNER SPONGE	220.50	1 PC	Re form 220.50	✓
13 BONNET INNER RUBBER	56.20	1 PC	CM 56.20	✓
14 HEADLAMPS	2,677.90	2 PCS	5,355.80	4+
15 HEADLAMP LOWER BRACKETS	24.00	2 PCS	48.00	?
16 AIR-CON CONDENSER	663.00	1 PC	663.00	?
17 RADIATOR	799.00	1 PC	799.00	?
18 FRT SUPPORT PANEL	882.20	1 PC	882.20	?
19 FRONT SUPPORT PANEL TOP GARNISH	52.80	1 PC	CM 52.80	✓
20 FRONT SUPPORT PANEL TOP GARNISH CLIPS	3.50	6 PCS	SM 21.00	✓
21 REAR BUMPER UPPER	446.50	1 PC	R 446.50	✓
22 REAR BUMPER LOWER	351.40	1 PC	R 351.40	✓
23 REAR BUMPER REINFORCEMENT	270.80	1 PC	R 270.80	✓
24 REAR BUMPER TOW COVER	5.70	1 PC	SM 5.70	X
25 REAR BUMPER REFLECTORS	102.90	2 PCS	205.80	?
26 REAR BUMPER CLIPS	3.50	6 PCS	SM 21.00	✓
27 REAR REVERSE SENSORS (CENTRE)	140.20	2 PCS	short R 280.40	✓
28 REAR TAILGATE	1,758.90	1 PC	R 1,758.90	✓
29 TAILGATE LOGO	30.70	1 PC	SM 30.70	✓
30 TAILGATE LOWER OUTER GARNISH	202.00	1 PC	CM 202.00	✓
31 TAILGATE EMBLEM (TUCSON)	29.10	1 PC	SM 29.10	✓
32 TAILGATE INNER LOCK	677.00	1 PC	DIY 677.00	✓
33 TAILGATE INNER RUBBER	126.90	1 PC	DIY 126.90	50612
34 TAILGATE AUTO LOCK SENSOR	80.20	1 PC	R 80.20	?
35 REAR END PANEL	739.10	1 PC	R 739.10	✓
36 REAR WINDSCREEN GLASS MOULDING	440.90	1 PC	440.90	?
			18,296.20	
	Less 20%		3,659.24	14,636.96

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 03/04/2021
 TP Veh Reg No: SLN8341Y

Estimate No: ES2190314/YISHUN
 Date: 05 Apr 2021
 Policy No: 5118262173
 Veh Reg No: SKW6586K
 Make/Model: HYUNDAI HYUNDAI
 TL TUCSON 2.0 GLS AT
 Chassis No: KMHJ3813MGU071470
 Engine No: G4NAFU075631
 Reg. Date: 11/11/2015

Estimate Repair Cost to Vehicle No :SKW6586K

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Special Net				
37 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	
38 REAR NUMBER PLATE	35.00	1 PC	35.00	
			75.00	75.00
Labour				
39 TOWING	50.00	1 LA	50.00	
40 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	
41 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REFLECTORS, REAR WIPER ASSY, SPOILER & THIRD BRAKE LIGHT, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR FENDERS & COMPARTMENT AND REALIGN THE SAME	800.00	1 LA	800.00	
42 PUTTY & RESPRAY ON TAILGATE, REAR PANEL, GARNISH, REAR COMPARTMENT, REAR FENDERS	900.00	1 LA	900.00	
43 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	
44 REMOVE & REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET & ATTACHMENT, RADIATOR & MOTOR, TO KNOCK & REPAIR FRT BOTH FENDERS & REALIGN THE SAME	700.00	1 LA	700.00	
45 PUTTY & RESPRAY ON FRT BUMPER, BONNET, FRT	700.00	1 LA	700.00	
46 REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR, AUTO LOCK SENSOR & RESET SYSTEM	60.00	1 LA	60.00	
47 RUSTPROOFING	60.00	1 LA	60.00	
			3,470.00	3,470.00

Total S\$ 18,181.96

Add GST @ 7% 1,272.74

Total Amount Payable S\$ 19,454.70

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE