



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

03/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AIG.

Jashin.

Accident date: 01/04/2021

Estimated repair cost for vehicle no: SMQ2631Y TOYOTA PRIUS PLUS 1.8 A '19

CHASSIS: JTDZS3EU30J052313

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>rehand</i>		\$865.25 576
2	1	Front Bumper Emblem Logo <i>per</i>		\$121.15 72
3	1	Front Bumper Number Plate <i>Best</i>		\$50.00 ✓
4	2	Front Bumper Side Retainer <i>per</i>	\$171.78	\$343.56 236
5	1	Front Bumper Reinforcement <i>per</i>		\$561.60 ✓
6	1	Front Bumper Reinforcement Foam <i>cracked</i>		\$125.00 ✓
7	1	Front Bumper Center Grille <i>cracked</i>		\$561.90 ✓
8	8	Front Bumper Center Grille Clip <i>per</i>	\$6.50	\$52.00 20
9	1	Front Bumper Lower <i>per</i>		\$571.00 ✓
10	1	Front Bumper Lower Garnish <i>rehand</i>		\$371.00 ✓
11	1	Front Bumper Lower Cover <i>per</i>		\$98.00 ✓
12	2	Front Bumper Fog Lamp <i>3rd</i>	\$731.10	\$1,462.20 ✓
13	2	Front Bumper Towing Cover <i>per</i>	\$121.10	\$242.20 ✓
14	1	Front Support Panel <i>3rd</i>		\$1,712.45 ✓
15	2	Front Support Panel Air Guide <i>per</i>	\$65.00	\$130.00 ✓
16	1	Front Condensor <i>per</i>		\$1,210.40 ✓
17	1	Front Air-Con Condenser Fan Motor Assy <i>per</i>		\$971.25 ✓
18	1	Front Radiator <i>per</i>		\$1,675.35 ✓
19	1	Front Radiator Fan Motor Assy <i>per</i>		\$825.00 ✓
20	2	Front Head Lamp <i>cracked</i> RH CRA	\$2,781.10	\$5,562.20 2,625.00
21	1	Front Head Lamp Lower Bracket <i>per</i>	\$185.00	\$185.00 ✓
22	1	Rear Boot Lid <i>Repris</i>		\$1,235.70 ✓
23	2	Rear Boot Lid Hinge <i>per</i>	\$274.00	\$548.00 ✓
24	2	Rear Boot Lid Shock Absorber <i>per</i>	\$461.00	\$922.00 ✓
25	1	Rear Boot Lid Emblem Logo <i>3rd</i>		\$125.00 ✓
26	1	Rear Boot Lid Prius+ Logo <i>per</i>		\$124.00 ✓

27	1	Rear Boot Lid Hybrid Logo	new		\$130.00	✓
28	1	Rear Boot Lid Number Plate	new		\$50.00	✓
29	1	Rear Boot Lid Inner Lock	new		\$361.00	✓
30	1	Rear Boot Lid Inner Weatherstrip	new		\$323.00	✓
31	1	Rear Boot Lid Inner Trim Board	new		\$681.90	✓
32	10	Rear Boot Lid Inner Trim Board Clip	new	\$6.50	\$65.00	✓
33	1	Rear Boot Lid Windscreen Seal	new		\$105.00	✓
34	1	Rear Fender Inner Trim Board	new	\$638.90	\$638.90	✓
35	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	30
36	1	Rear Bumper	new		\$549.00	✓
37	1	Rear Bumper Lower Lid	new		\$726.00	612
38	1	Rear Bumper Lower Cover	new		\$187.00	✓
39	10	Rear Bumper Clip	new	\$6.50	\$65.00	30
40	2	Rear Bumper Side Retainer	new	\$108.00	\$216.00	✓
41	2	Rear Bumper Side Reflector	new	\$58.00	\$116.00	✓
42	1	Rear Bumper Reverse Sensor	new		\$780.00	200(SN)
43	2	Rear Bumper Side Reflector	new	\$180.00	\$360.00	✓
44	1	Rear Bumper Reinforcement	Dented		\$625.00	350
45	1	Rear End Panel	Dented		\$896.00	645
46	1	Rear End Panel Top Garnish	new		\$358.00	292
47	1	Rear Tool Sponge	new		\$385.50	✓
48	2	Rear Tail Lamp	new	\$489.00	\$978.00	✓ NN
49	2	Rear Tail Lamp Lower Bracket	new	\$42.00	\$84.00	✓
50	4	Rear Tail Lamp Clip	new	\$8.00	\$32.00	20

51 2 Rear Bumper Reinforcement Bracket
Dented 219.20 ✓

13200.50
9900.37

Subtotal :- \$29,467.51

S.N : 200

Labour charges

To remove & refit air-con condenser, radiator, fan motor, & top up gas	\$280.00	✓
To remove & refit cushion & trim board	\$280.00	60
To remove & refit reverse sensor	\$100.00	50
To check wiring	\$80.00	60
Tuff kote	\$100.00	60
Panel beating	\$2,200.00	1000
	700.00	

Spray painting

2130

800.00

~~\$2,000.00~~

~~1000~~

Subtotal :- \$5,040.00

Total:- \$34,507.51

~~total: 11230.37~~

~~c/s: 9.81k~~

~~0.92k~~

9.81k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: