

A.S.S. REC. BY: Tough

REF:

CC4/A192004314/TIR 93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

VincentVeh No: SHC6768T Yr Regn: 2021, Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i30 C.C. 1580Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 12939 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMAC851CV64241045

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 6/4/21Survey held at Primer Shop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Formed: _____

Lump Sum / L.B.I. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Apr-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6768 T

1 pc	Rear bumper	\$	459.40	R7
1 pc	Rear bumper reinforcement	\$	294.80	?
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00	\$	30.00	?
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	X
2 pcs	Rear bumper n/s & o/s stay @ \$138.10	\$	276.20	X
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10	\$	66.20	X
1 pc	Rear bumper lower moulding centre	\$	216.50	de -
1 pc	Rear bumper lower cover	\$	47.50	X
1 pc	Rear bumper cap hook	\$	9.10	X
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80	X
		\$	1,478.50	
		Less 20%	\$	295.70
			\$	1,182.80

S/N

1 set	Rear bumper clips	\$	48.00	X
1 set	Reverse sensor	\$	280.00	200
1 pc	Rear number plate with casing	\$	50.00	X
1 pc	Rear bumper top protector	\$	80.00	X
Sundry		\$	50.00	X
To check wiring		\$	50.00	X
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc		\$	650.00	200
To putty and spray painting on rear bumper, end panel, Rear bumper lower cover (Black)		\$	600.00	200
To apply rustproofing on the repaired and replaced panels.		\$	120.00	X
		\$	3,410.80	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495449
WP 6/4/21 @ 530pm
2 days
1/2 resurvey new parts, after upon
taufik @ 14 days
M.L.

Vehicle Registration Details

Vehicle No. SHC6768T	Make/ Model HYUNDAI/AE IONIQ HEV FL 1.6 DCT	Vehicle Scheme Revised Taxi (Company)
Current Propellant Petrol-Electric	Chassis No. KMHC851CVLU241045	Vehicle Type Public Transport Taxi (Motor Car)

Owner's Details

Owner Name:

PREMIER TAXIS PTE. LTD.

NRIC/Passport/Company Cert No.:

200304975H

Mailing Address:

-

Owner ID Type:

Company

Registered Address

**23 CHANGI SOUTH AVENUE 2 #04-03
SINGAPORE 486443**

Birth Date

-

Registration Details

Previous Vehicle No.:

-

Original Registration Date:

13 Jan 2021

No. of Transfers:

0

Effective Date of Ownership:

13 Jan 2021

Registration Date:

13 Jan 2021

IU Label No.:

1050549329

Vehicle Specifications

Engine No.:

G4LELU041275

Year of Manufacture:

2020

Chassis No.:

KMHC851CVLU241045

Motor No.:

PM04LAU333DJ

Primary Colour:

Silver

Secondary Colour:

-

Passenger Capacity:

4

Engine Capacity / Power Rating :

1580 cc / 32.0 kW

Maximum Power Output:

103.6 kW (138 bhp)

Max Unladen Weight:

1361 kg

Maximum Laden Weight:

1870 kg

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

-

Vehicle Attachment 3:

-

Additional Registration Fee (ARF) and COE Information

Open Market Value:

\$24,646.00

Additional Registration Fee Rate:

First \$20,000.00 (100%), next \$4,646.00 (140%)

Actual ARF Paid:

\$5,000.00

Vehicle Lifespan Expiry Date:

12 Jan 2029

OPC Cash Rebate Eligibility:

No

QP during COE Bidding Exercise:

\$0.00

COE No.:

2021011301002031H

COE Expiry Date:

12 Jan 2029

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Registration Category:

A - Car up to 1600cc & 97kW (130bhp)

Quota Premium (QP) / Prevailing Quota Premium :

- / \$38,137.00

PQP Paid

\$30,510.00

QP (Regn Cat):

--

PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

12 Jan 2029

Minimum PARF Benefit:

\$3,000.00