

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Apr-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6768 T

1 pc	Rear bumper	\$	459.40	Ry
1 pc	Rear bumper reinforcement	\$	294.80	? ch
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00	\$	30.00	X ny
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	X ny
2 pcs	Rear bumper n/s & o/s stay @ \$138.10	n/s X ny \$	276.20	X s bt
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10	\$	66.20	X ny
1 pc	Rear bumper lower moulding centre	\$	216.50	de
1 pc	Rear bumper lower cover	\$	47.50	X 7 X ny
1 pc	Rear bumper cap hook	\$	9.10	X
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$	63.80	X
		\$	1,478.50	649.40
		Less 20%	\$	295.70
			\$	1,182.80

S/N

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear number plate with casing
1 pc	Rear bumper top protector

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sundry

To check wiring

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc

To putty and spray painting on rear bumper, end panel, Rear bumper lower cover (Black)

To apply rustproofing on the repaired and replaced panels.

\$	48.00	X ny
\$	280.00	200 X ny
\$	50.00	X
\$	80.00	X ny
\$	50.00	X
\$	50.00	X
\$	120.00	30
\$	180.00	X ny
\$	650.00	200
\$	600.00	200
\$	120.00	X ny
\$	3,410.80	430

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495741 949.52
WP 6/4/21 @ 530pm 2 days
2 days
1/2 Resurvey new parts, after upon
Taufik @ LKK Auto
M.C.