

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0277/2021/HR
DATE : 1-Apr-21
WIP : 21811

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Dear Rasul,

17 days - ok - Carrine

15/9/2021

OWNER'S NAME : MS LEE SWEE LING CHERYL
ADDRESS : 46 ALMOND CRESCENT
SINGAPORE 677800
TELEPHONE : HP +65 81101773
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100473850-04
VEHICLE NO : **SKT 9574 R**
MODEL CODE : A4 1.8 FSI MU
MODEL YEAR : 26/6/2015
ENGINE NO : CJE 100458
CHASSIS NO : WAUZZZ8K6FA115080
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Mar-21
PLACE OF ACCIDENT : PIE TOWARDS CHANGI, NEAR LAMPOST NO 1794

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 9574 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE & REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$	280.00
2	TO REMOVE & TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM & WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	\$	280.00
3	TO RENEW REAR WINDSCREEN & LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	\$	600.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN & LHS 1/4 GLASS.	S/N \$	400.00		
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN & 1/4 GLASS.	S/N \$	200.00	\$	200.00
6	TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE & RELAY TRAYS, ELECTRICAL & AUDIO EQUIPMENT. INSPECT FOR DAMAGE & RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$	1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,160.00	\$	2,760.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 9574 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 2,760.00
7	TO REMOVE & REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER & DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	\$ 1,400.00
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	
9	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	
10	TO PUT THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 1,800.00	
11	TO DISMANTLE & RENEW REAR BUMPER & REAR LID. TO CUT OUT & WELD LHS REAR FENDER, LHS CONNECTING PLATE, LHS BOTTOM PLATE & LHS INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,100.00	\$ 4,500.00
12	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, LHS SILL PANEL, LHS CONNECTING PLATE, LHS BOTTOM PLATE, LHS INNER SIDE PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES & END PANELLING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION & JOINT SEALER WORKS.	\$ 7,700.00	\$ 3,575.00
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
14	Supplementary Estimate		\$ 1,500.00
TOTAL LABOUR CHARGES		: \$ 24,432.00	\$ 13,927.00



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0277/2021/HR
Date 28-Jun-21
Service Advisor GLORY
Pages 1 of 1
Regn No SKT 9574 R
Model No A4 1.8 FSI MU

Quantity	Description	Unit Price	Amount
Labours			
1	TO CUT OUT AND WELD REAR END PANEL.	\$ 1,500.00	\$ 1,500.00
GRAND TOTAL		\$ 1,500.00	\$ 1,500.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,451.00	\$ 1,960.80
2	REAR BUMPER FIXING APRTS	1	\$ 228.00	
3	REAR BUMPER SPOILER	1	\$ 267.00	\$ 213.20
4	REAR BUMPER CARRIER	1	\$ 681.00	
5	REAR BUMPER HOLDER BRACKET - LH / RH	2	\$ 446.00	
6	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 89.00	
7	REAR BUMPER UPPER GUIDE SECTION - LH / RJ	2	\$ 47.00	\$ 18.56
8	REAR BUMPER PIN	2	\$ 12.00	
9	REAR BUMPER SECURING STRIP	1	\$ 14.00	
10	REAR BUMPER PARKING AID SENSOR	3	\$ 732.00	\$ 195.12
11	REAR BUMPER PARKING AID SENSOR SEAL	4	\$ 6.00	\$ 4.16
12	REAR BUMPER WIRING SET	1	\$ 515.00	
13	REAR BOOT LID	1	\$ 3,361.00	
14	REAR BOOT LID ATTACHMENT PARTS	1	\$ 75.00	
15	REAR BOOT LID HINGE - LH / RJ	1	\$ 512.00	
16	REAR BOOT LID GASKET	1	\$ 205.00	\$ 164.00
17	REAR BOOT LID ADHESIVE	1	\$ 19.00	\$ 14.88
18	"A4" EMBLEM	1	\$ 99.00	\$ 79.04
19	"AUDI" EMBLEM	1	\$ 138.00	\$ 110.00
20	"TFSI" EMBLEM	1	\$ 99.00	\$ 79.04
SUB TOTAL SPARE PARTS		:	\$ 9,996.00	\$ 2,838.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>	\$	2,838.80
21	REAR SIDE PANEL - LH	1 \$	4,003.00 \$	2,915.20
22	REAR WINDOW	1 \$	1,128.00	
23	REAR SIDE WINDOW - LH	1 \$	305.00 \$	243.60
24	PRIMER	1 \$	20.00 \$	15.76
25	BOTTOM OUTER FLOOR PLATE - LH	1 \$	403.00	
26	REAR SIDE PANEL CONNECTING PLATE - LH	1 \$	340.00 \$	271.60
27	REAR OUTER WHEEL HOUSING - LH	1 \$	647.00	
28	REAR SIDE PANEL - LH	1 \$	206.00 \$	164.40
29	REAR WHEEL HOUSING LINER - LH	1 \$	222.00 \$	177.20
30	REAR WHEEL HOUSING LINER ATTACHMENT PARTS - LH	1 \$	45.00	
31	REAR SIDE PANEL VENT TRIM	1 \$	72.00 \$	57.52
32	OUTER TAIL LIGHT - LH	1 \$	1,075.00 \$	860.00
33	INNER TAIL LIGHT - LH	1 \$	901.00 \$	720.80
34	REAR CROSS PANEL TRIM	1 \$	189.00	
35	REAR BOOT COMPARTMENT TRIM - LH	1 \$	413.00 \$	330.40
36	REAR BOOT COMPARTMENT FLOOR COVERING	1 \$	708.00	
37	REAR BOOT LID TRIM	1 \$	278.00	
38	REAR BOOT WARNING TRIANGLE RETAINER	1 \$	58.00	
39	REAR BOOT WARNING TRIANGLE	1 \$	193.00	
40	REAR DOOR SILL TRIM STRIP - LH	1 \$	89.00	
SUB TOTAL SPARE PARTS		:	\$ 11,295.00 \$	8,595.28

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 8,595.28
41	1/ GLASS SEALANT	S/N \$	100.00	\$ 100.00
42	ACRYLIC SEALANT	S/N \$	180.00	\$ 180.00
43	CAVITY WAX	S/N \$	140.00	\$ 140.00
44	STONE CHIP	S/N \$	180.00	\$ 180.00
45	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
46	REAR WINDSCREEN SEALANT	S/N \$	200.00	\$ 200.00
47	SUPPLEMENTARY	\$	312.50	\$ 250.00
48	SUNDRIES	\$	400.00	\$ 14.88
TOTAL SPARE PARTS			: \$ 23,083.50	\$ 9,940.16
TOTAL LABOUR CHARGES			: \$ 24,432.00	\$ 13,927.00
GRAND TOTAL			: \$ 47,515.50	\$ 23,867.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-04/06/21



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0277/2021/HR
Date 28-Jun-21
Service Advisor GLORY
Pages 1 of 1
Regn No SKT 9574 R
Model No A4 1.8 FSI MU

Quantity	Description	Unit Price	Amount
Parts			
1	End Panel	BT \$ 312.50	\$ 250.00
GRAND TOTAL		\$ 312.50	\$ 250.00

For Premium Automobiles Pte Ltd

Authorised Signature