

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>de /</i>	1	\$ 2,451.00	<i>1960.80</i>
2	REAR BUMPER FIXING APRTS <i>? Xmm</i>	1	\$ 228.00	
3	REAR BUMPER SPOILER <i>scr /</i>	1	\$ 267.00	<i>213.20</i>
4	REAR BUMPER CARRIER <i>? Xsu</i>	1	\$ 681.00	
5	REAR BUMPER HOLDER BRACKET <i>LH / RH</i>	2	\$ 446.00	
6	REAR BUMPER GUIDE SECTION <i>LH / RH</i>	2	\$ 89.00	
7	REAR BUMPER UPPER GUIDE SECTION <i>LH / RJ</i>	1	\$ 47.00	<i>18.56</i>
8	REAR BUMPER PIN <i>? Xmm</i>	1	\$ 12.00	
9	REAR BUMPER SECURING STRIP <i>? Xsu</i>	1	\$ 14.00	
10	REAR BUMPER PARKING AID SENSOR <i>dis -</i>	1	\$ 732.00	<i>195.12</i>
11	REAR BUMPER PARKING AID SENSOR SEAL <i>re /</i>	1	\$ 6.00	<i>4.16</i>
12	REAR BUMPER WIRING SET <i>? Xsu</i>	1	\$ 515.00	
13	REAR BOOT LID <i>Xsu</i>	1	\$ 3,361.00	
14	REAR BOOT LID ATTACHMENT PARTS <i>? Xsuc</i>	1	\$ 75.00	
15	REAR BOOT LID HINGE - LH / RJ <i>? Xsu</i>	1	\$ 512.00	
16	REAR BOOT LID GASKET <i>re /</i>	1	\$ 205.00	<i>164.00</i>
17	REAR BOOT LID ADHESIVE <i>re /</i>	1	\$ 19.00	<i>14.88</i>
18	"A4" EMBLEM <i>re /</i>	1	\$ 99.00	<i>79.04</i>
19	"AUDI" EMBLEM <i>re /</i>	1	\$ 138.00	<i>116</i>
20	"TFSI" EMBLEM <i>re /</i>	1	\$ 99.00	<i>79.04</i>
SUB TOTAL SPARE PARTS		:	\$ 9,996.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR SIDE PANEL - LH <i>buc/</i>	1	\$	4,003.00	<i>2915.20</i>
22	REAR WINDOW <i>2 Xnn</i>	1	\$	1,128.00	
23	REAR SIDE WINDOW - LH <i>nee/</i>	1	\$	305.00	<i>243.60</i>
24	PRIMER <i>ne/</i>	1	\$	20.00	<i>15.76</i>
25	BOTTOM OUTER FLOOR PLATE - LH <i>? Xsu</i>	1	\$	403.00	
26	REAR SIDE PANEL CONNECTING PLATE - LH <i>? bt/</i>	1	\$	340.00	<i>271.60</i>
27	REAR OUTER WHEEL HOUSING - LH <i>? Xsu</i>	1	\$	647.00	
28	REAR SIDE PANEL - LH <i>? bt/</i>	1	\$	206.00	<i>164.40</i>
29	REAR WHEEL HOUSING LINER - LH <i>at/</i>	1	\$	222.00	<i>177.20</i>
30	REAR WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>Xnn</i>	1	\$	45.00	
31	REAR SIDE PANEL VENT TRIM <i>di/</i>	1	\$	72.00	<i>57.52</i>
32	OUTER TAIL LIGHT - LH <i>bo/</i>	1	\$	1,075.00	<i>860.00</i>
33	INNER TAIL LIGHT - LH <i>su/</i>	1	\$	901.00	<i>720.80</i>
34	REAR CROSS PANEL TRIM <i>? Xsu</i>	1	\$	189.00	
35	REAR BOOT COMPARTMENT TRIM - LH <i>de/</i>	1	\$	413.00	<i>330.40</i>
36	REAR BOOT COMPARTMENT FLOOR COVERING <i>Xsu</i>	1	\$	708.00	
37	REAR BOOT LID TRIM <i>Xsu</i>	1	\$	278.00	
38	REAR BOOT WARNING TRIANGLE RETAINER <i>Xsu</i>	1	\$	58.00	
39	REAR BOOT WARNING TRIANGLE <i>Xsu</i>	1	\$	193.00	
40	REAR DOOR SILL TRIM STRIP - LH <i>? Xsu</i>	1	\$	89.00	
SUB TOTAL SPARE PARTS		:	\$	11,295.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	1/ GLASS SEALANT <i>neu</i>	S/N	\$ 100.00	/	
42	ACRYLIC SEALANT <i>neu</i>	S/N	\$ 180.00	/	
43	CAVITY WAX <i>neu</i>	S/N	\$ 140.00	/	
44	STONE CHIP <i>neu</i>	S/N	\$ 180.00	/	
45	METAL FILLER POWDER <i>neu</i>	S/N	\$ 280.00	/	
46	REAR WINDSCREEN SEALANT <i>neu</i>	S/N	\$ 200.00	/	
47	SUNDRIES <i>? neu</i>		\$ 400.00	<i>14.88</i>	
TOTAL SPARE PARTS		:	\$ 22,771.00		
TOTAL LABOUR CHARGES		:	\$ 24,432.00		
GRAND TOTAL		:	\$ 47,203.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.