

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SONG ZHAOSHAN, GERALD	Cust No/Name /SONG ZHAOSHAN, GERALD
428 TAMPINES STREET 41	Reg No/Reg Date SMV1622D / 18/09/202
#09-471	Date In/Mileage / 0
SINGAPORE 520428	Chassis No KNAD6811VL6382809
Contact No Mobile: 90098764	Engine No G3LCKP165734
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim SEN DEEP SIENNA BRO/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	05/04/2021/ 16:30	BLC	442 / CocoLu	31551				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000									400.00
RENEW FRT BUMPER									350.00
E PNT98000									50.00
SPRAY PAINT FOR FRT BUMPER									30.00
M SUNDRY									120.00
FRT NUMBER PLATE WITH FRAME									2000.00
A 90000001									1050.00
CHECK WIRING & ELECTRICAL SYSTEM									60.00
A 10028901									240.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									80.00
USING HI-SCAN PRO TEST									40.00
E PNT88000									50.00
RENEW REAR BUMPER, TAILGATE, REAR END PANEL									80.00
E PNT98000									400.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL									20.00
E PNT88000									476.00
REMOVE & INSTALL PARKING SENSOR									324.00
E PNT88000									
REMOVE & INSTALL TAILGATE GLASS									
M SUNDRY									
APPLY SEALANT FOR TAILGATE GLASS									
M SUNDRY									
C&C LOGO									
M SUNDRY									
REAR NUMBER PLATE WITH FRAME									
M SUNDRY									
APPLY SEALANT FOR ACCIDENT PORTION									
A 90000001									
RENEW REAR EXHAUST SYSTEM									
M SUNDRY									
Sundry						1.00	476.00	00.00	476.00
M COVER-FR BUMPER UPR						1.00	324.00	00.00	324.00
M GRILLE ASSY-RADIATOR									

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



GST Reg No : MR-8500111-X

ESTIMATE

Co Reg No : 199405410K

Invoice Name & Address		Owner Name & Vehicle Info	
SONG ZHAOSHAN, GERALD		Cust No/Name	/SONG ZHAOSHAN, GERALD
428 TAMPINES STREET 41		Reg No/Reg Date	SMV1622D / 18/09/202
#09-471		Date In/Mileage	/ 0
SINGAPORE 520428		Chassis No	KNAD6811VL6382809
Contact No Mobile: 90098764		Engine No	G3LCKP165734
		Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
		Colour/Trim	SEN DEEP SIENNA BRO/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	05/04/2021/ 16:30	BLC	442 / CocoLu	31551				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	MOULDING-FRONT BUMPER A/INTAKE	OR				1.00	61.00	00.00	61.00
M	GRILLE-FRONT BUMPER	X AN				1.00	96.00	00.00	96.00
M	ABSORBER-FRONT BUMPER ENERGY	OR				1.00	98.00	00.00	98.00
M	COVER-RR BUMPER LWR	BR				1.00	366.00	00.00	366.00
M	SKID PLATE-RR BUMPER	OR				1.00	122.00	00.00	122.00
M	COVER-RR BUMPER SIDE UNDER	OR				1.00	62.00	00.00	62.00
M	MOULDING ASSY-RR BUMPER SIDE, R	CUT				1.00	152.00	00.00	152.00
M	MOULDING ASSY-RR BUMPER SIDE, L	X AN				1.00	152.00	00.00	152.00
M	LAMP ASSY-REAR FOG & R/REFL, RH	OR				1.00	111.00	00.00	111.00
M	LAMP ASSY-REAR FOG & R/REFL, LH	X AN				1.00	111.00	00.00	111.00
M	ULTRASONIC SENSOR ASSY-BWS	X AN				1.00	189.00	00.00	189.00
P	ULTRASONIC SENSOR ASSY-BWS	X AN				2.00	189.00	00.00	378.00
M	WIRING HARNESS-BWS EXT	X AN				2.00	189.00	00.00	378.00
M	BRACKET-RR BEAM LWR MTG, LH	X AN				1.00	245.00	00.00	245.00
M	BRACKET-RR BEAM LWR MTG, RH	OR				1.00	7.00	00.00	7.00
P	BRACKET-RR BEAM UPR MTG	OR				5.00	5.00	00.00	5.00
M	STAY-RR BUMPER LH	X AN				1.00	7.00	00.00	7.00
M	STAY-RR BUMPER RH	X AN				1.00	55.00	00.00	55.00
M	BEAM-RR BUMPER	OR				1.00	55.00	00.00	55.00
M	ANTENNA ASSY-SMARTKEY	X AN				1.00	419.00	00.00	419.00
M	PANEL ASSY-TAIL GATE	OR				1.00	32.00	00.00	32.00
M	GARNISH-T/GATE UPR, LH	OR				1.00	1010.00	00.00	1010.00
M	GARNISH-T/GATE UPR, RH	OR				1.00	66.00	00.00	66.00
M	EMBLEM-TURBO G.D.I	OR				1.00	66.00	00.00	66.00
M	LOGO ASSY-KIA SUB	OR				1.00	38.00	00.00	38.00
M	EMBLEM-STONIC	OR				1.00	51.00	00.00	51.00
M	PROTECTOR-HEAT REAR	OR				1.00	26.00	00.00	26.00
M	MUFFLER ASSY-REAR	OR				1.00	26.00	00.00	26.00
M	PANEL ASSY-BACK	OR				1.00	49.00	00.00	49.00
M	TRIM ASSY-RR TRANSVERSE	OR				1.00	49.00	00.00	49.00

STER (CLKK)
5/4/21, 5:00 PM
OD-NH AL
EXPER. ?

Confirm & accepted by:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

P/P
By BCL sy
9 dya

7% GST on	11060.00	Nett	11,060.00
			774.20
		Total Payable	11,834.20

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.