



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.04.2021
Emailed : 20.04.2021, 2.45pm
Date Survey : 05.04.2021

VEHICLE NO : SMV 1622 D
MODEL : KIA STONIC 1.0 A SX
WIP : 31551

Material	:	\$	<u>3,225.60</u>
Labour	:	\$	<u>4,660.00</u>
Sub-Total	:	\$	<u>7,885.60</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>7,885.60</u>
GST 7%	:	\$	<u>551.99</u>
Grand Total	:	\$	<u>8,437.59</u>
Finalise By/Date	:		<u>LOI / 20/04/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 06/04/2021	Cust No/Name	/SONG ZHAOSHAN, GERALD
	Reg No/Reg Date	SMV1622D / 18/09/2020
	Date In/Mileage	06/04/2021/ 11310
	Chassis/Package	KNAD6811VL6382809 /#
	Engine No	G3LCKP165734
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	SEN DEEP SIENNA BRO/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	20/04/2021/ 11:57	BLC	260 / AiTing	31551
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 REPLACE FRONT DAMAGED PARTS, REPAIR FRONT BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 400.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHE RAFFECTED AREAS TO THE SAME					✓ 350.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM					✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE					✓ 120.00
E PNT88000 REPLACE REAR DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REPAIR ALL OTHER AFFECTED AREAS, AJDUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓ 800.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, AND ALL OTHER AFFECTED AREAS TO THE SAME					✓ 700.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR					✓ 60.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST					✓ 240.00
M SUNDRY APPLY SEALANT ON TAILGATE GLASS					✓ 80.00
M SUNDRY SUPPLY C&C LOGO					✓ 40.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS					✓ 40.00
A 90000001 REPLACE REAR EXHAUST MUFFLER AND CENTRE EXHAUST PIPE					✓ 200.00
M SUNDRY SUNDRIES					✓ 20.00
S SPECIALISTJOB SUPPLY BOTH FRONT & REAR LICENSE PLATE WITH FRAME (\$50 + \$50)					✓ 100.00

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SONG ZHAOSHAN, GERALD Reg No/Reg Date SMV1622D / 18/09/2020 Date In/Mileage 06/04/2021/ 11310 Chassis/Package KNAD6811VL6382809 /# Engine No G3LCKP165734 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim SEN DEEP SIENNA BRO/ WK SATURN BLACK
06/04/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	20/04/2021/ 11:57	BLC	260 / AiTing	31551

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR END PANEL, & REPAIR REAR FLOOR PANEL → Supp.				600.00
E PNT88000 REMOVE & REINSTALL REAR COMPARTMENT TRIMS & SEATS TO FACILITATE REPAIR → Supp.				180.00
E PNT98000 RESPRAY ON REAR END PANEL, & REAR FLOOR PANEL → Supp.				700.00
X MOULDING-FRONT BUMPER A/INTAKE	1.00	✓ 61.00	20.00	48.80
X ABSORBER-FRONT BUMPER ENERGY	1.00	✓ 98.00	20.00	78.40
X COVER-RR BUMPER LWR	1.00	✓ 366.00	20.00	292.80
X SKID PLATE-RR BUMPER	1.00	✓ 122.00	20.00	97.60
X COVER-RR BUMPER SIDE UNDER	1.00	✓ 62.00	20.00	49.60
X MOULDING ASSY-RR BUMPER SIDE, R	1.00	✓ 152.00	20.00	121.60
X LAMP ASSY-REAR FOG & R/REFL, RH	1.00	✓ 111.00	20.00	88.80
X BRACKET-RR BEAM LWR MTG, RH	1.00	✓ 5.00	20.00	4.00
X BEAM-RR BUMPER	1.00	✓ 419.00	20.00	335.20
X PANEL ASSY-TAIL GATE	1.00	✓ 1010.00	20.00	808.00
X GARNISH-T/GATE UPR, LH	1.00	✓ 66.00	20.00	52.80
X GARNISH-T/GATE UPR, RH	1.00	✓ 66.00	20.00	52.80
X EMBLEM-TURBO G.D.I	1.00	✓ 38.00	20.00	30.40
X LOGO ASSY-KIA SUB	1.00	✓ 51.00	20.00	40.80
X EMBLEM-STONIC	1.00	✓ 26.00	20.00	20.80
X MUFFLER ASSY-REAR	1.00	✓ 665.00	20.00	532.00
X PANEL ASSY-BACK	1.00	✓ 345.00	20.00	276.00
X BRACKET-RR BEAM UPR MTG	1.00	✓ 7.00	20.00	5.60
X MUFFLER ASSY-CENTER → Supp.	1.00	362.00	20.00	289.60
Z TEXT AIG OD CLAIM. DOA : 05.04.21 SURVEYOR STEVE LKK 05.04.21 POLICY NO: 2070136022				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	3,225.60	Nett	7,885.60
Labour	4,380.00	7% GST on	551.99
Standard Menu	0.00		
Specialist Job	100.00	Total Payable	8,437.59
Diagnostics Job	0.00		
Sundry/Others	180.00		
Total(w/o GST)	7,885.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.


INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMV 1622 D**

<u>Materials</u>		<u>Cost (\$)</u>
1	Muffler assy-Center	362.00 ✓ BT
Total Materials		362.00
Less 20% discount		72.40
Total after discount		289.60
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace rear end panel, & repair rear floor panel	600.00 ✓
2	Remove & reinstall rear compartment trims, & seats to facilitate repair	180.00 ✓
3	Respray on rear end panel, & rear floor panel	700.00 ✓
Total labour		1,480.00
Total amount		1,769.60
7% GST		123.87
Grand total		<u>\$ 1,893.47</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: 24V1622DWIP: 3551 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Lamp Rear Fog + Reflector RH	? / SUPP		/ RR	
2	Bracket RR Beam Lower Mtg RH	? / SUPP		/ RR	
3	Bracket RR Beam Upper	? / SUPP		/ RR	
4	Panel Assy - Back	? / SUPP		/ RR	
5	Absorber - Front Bumper Energy	? / SUPP		/ RR	
6	Renew End panel repair floor panel	? / SUPP		/ RR	
7	1.5 day \$600	? / SUPP		/ RR	
8	Spray paint RR End panel & RR compartment	? / SUPP		/ RR	
9	\$1700	? / SUPP		/ RR	
10	RR compartment & pins & seats \$100	? / SUPP		/ RR	
11	add 1 repair days - Total 10 days	? / SUPP		/ RR	
12	Center Muffler 4x	? / SUPP		/ RR	
13		? / SUPP		/ RR	
14		? / SUPP		/ RR	
15		? / SUPP		/ RR	
16		? / SUPP		/ RR	
17		? / SUPP		/ RR	
18		? / SUPP		/ RR	
19		? / SUPP		/ RR	
20		? / SUPP		/ RR	

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	12/4/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: StenacSURVEYOR: Steve



STONIC(YB CU../2020/G 1.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



11/11

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.

M-E-K-01-00-0243

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10