AFORTDELGRO ENGINEERING PTE LTD.

PAIR ESTIMATE*

VEHICLE NO

SHD3310U

MAKE

01/04/21

DEL	HYU- 140	CHIANG /NTUC				
Qty	Parts Description/ Labour		Туре	Unit Price	Amount	- 1 2
* == ==	1 REAR BUMPER COVER			200	\$1,106.00) pre
	2 REAR BUMPER BRACKET SIDE LH /R	RH		\$35.60	\$71.20	
	10 REAR BUMPER CLIPS			\$2.20	\$22.00	
	1 REAR BUMPER UNDER COVER				\$228.00	
	1 REAR BUMPER REINFORCEMENT				\$394.80	C. P.
	1 REAR PANEL GARNISH				\$57.50	
	1 REAR END PANEL	and the second s			\$526.70	KIY
	1 REAR PANEL LOWER				\$495.50	R
* 3 I	1 BOOTLID				\$2,171.90	R
	1 BOOTLID MOULDING				\$85.00	
	1 BOOTLID LOCK UPPER				\$114.90	
	2 REAR BUMPER REFLECTOR LH/RH	- 1		\$32.00	\$64.00	Kι
		1		1607-80-	\$5,337.50	
		20.00%			\$1,067.50	
	DISCOU	INTED TOTAL		1286.24	\$4,270.00	
1.5						
	1 REAR BUMPER MAT				\$50.00	
72.3	1 REAR BUMPER ADVERTISEMENT	LKK Auto Con			\$50.00	
	1 REVERSE-SENSOR	the Repairer p		painting	\$135.70	nu
		To display dama			\$222.13	
	Labour Charge	Parts prices areThird party surv	ey is on a "Wi	out Prejudice" basis		
	Panel Beating	No illegal mod fi Supplementary	ication(s) is all	wed	¢050.00	5
	Spray Painting Charge	is subject to fire	al approval from	Insurance Company	\$850.00 \$800.00	
	Check lighting	Acknowledged by	Repairer		\$50.00	
	Remove/refix reverse sensor	Signature:			\$60.00	_
	Tuff Kote	Date:	12		\$60.00	_
	то	TAL LABOUR		1370	\$1,820.00	
ESTIN				7810 20	\$1,020.00	
		ATE TOTAL		1570 2868.57 USJ 2300	\$6,312.13	
				US\$2300	¥ 0,012.13	
				0 L Am		
	This is an initial estimate based on a visual	inspection of the	above ve	icle. The final repair qua	antum will	
	be prepared after the vehicle is surveyed b	y a motor Survey	or appoint	ed by the insurance cor	npany.	

Taufmi 97495749 WP' 5/4/218 445 & 3dys WS Resurs affor repair faufm 2/hhours.com