



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT,
SINGAPORE 415875

Estimate for SKL1726P (BMW Z4)

Supplementary

Qty Spare Parts

- 1 RH taillamp
- 1 Rear bumper
- 1 Rear bumper RH side bracket
- 1 RH rear fender
- 1 RH rear fender petrol cover
- 1 RH front door
- 1 RH front door weatherstrip
- 1 RH front door outer handle
- 1 RH side rocker panel garnish
- 1 RH rear lower arm
- 1 RH rear knuckle arm
- 1 RH rear shock absorber
- 1 RH rear wheel bearing
- 1 RH rear top arm

List Price (\$)

	\$	2010	
	\$	663.40	NDX
	\$	✓ 1,389.40	CUTV
	\$	✓ 76.75	NECV
	\$	✓ 1,346.50	DDV
	\$	166.30	NDX
	\$	✓ 1,920.35	DDV
	\$	210.10	NNX
	\$	234.16	NDX
	\$	356.60	NDX
	\$	442.40	
	\$	1,256.90	
	\$	352.70	
	\$	136.60	
	\$	224.00	

@ 5%
 4733.00
 236.65
 4969.65

\$	8,776.16
-5% \$	438.81
\$	8,337.35

Qty Spare Parts

- 1set Rear bumper clips
- 1set RH side rocker panel garnish clips
- 1 RH rear tyre
- 1 RH rear sport rim

Special Nett (\$)

\$	30.00	80.00	NECV
\$		80.00	NNX
\$		550.00	NDX
\$	892.00	1,500.00	CUTV

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 800.00 1,500.00 ✓

Spray painting on affected panels

\$ 600.00 1,200.00 ✓

Check wiring and lighting system

\$ 50.00 80.00 ✓

Apply rust coating on affected areas

\$ 50.00 100.00 ✓

Transfer and replace RH front door inner mechanism to new door

\$ 120.00 ~~180.00~~ ✓

Remove and reinstall fuel tank, pipes, hoses and all attachments to assist repairs

\$ ~~180.00~~ NNX

Remove and reinstall RH rear inner trims, seats, boards, garnish and all attachments to assist repairs

\$ 100.00 ~~400.00~~ ✓

Remove, check and replace rear undercarriage parts

\$ ~~300.00~~ NNX

Conduct, test drive and adjust wheel alignment system

\$ ~~120.00~~ NNX

Remove, reinstall and re-adjust Hardtop Convertibles to assist repairs

\$ ~~700.00~~ NNX

Remove and reinstall rear bumper reverse sensors

\$ 60.00 ~~80.00~~ ✓

Total:

\$ 15,387.35

Survey

Resurvey

6/4/2021

7/4/2021

TGLim Inc

TGLim Inc

1330 hrs

1130 hrs

Lump sum repair

Repair days 7

PARTS 4496.35

SN 1002.00

LABOUR 1780.00

7278.35

@20% 1455.67

5822.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 5800/2

TGLim
Inc

17/4/2021