



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT,
SINGAPORE 415875

Estimate for SJX93L (Audi A6)
Supplementary

Qty Spare Parts

- 1 Bootlid centre emblem
- 1 Bootlid "A6" emblem
- 1 Bootlid "2.0T" emblem
- 1 Rear bumper
- 1 Rear bumper lower spoiler
- 1 Rear bumper towing cover
- 1 Rear bumper reinforcement
- 1 Rear bumper RH side retainer
- 1 Rear bumper LH side retainer
- 1 Rear bumper centre bracket
- 1 Rear bumper RH reverse sensor
- 1 Rear bumper LH reverse sensor
- 4 Rear bumper reverse sensor ring seals
- 1 Rear RH exhaust silencer
- 1 Rear RH exhaust silencer gasket

2014
List Price (\$)

\$ 100.85	117.00	} NECV
\$ 72.30	87.00	
\$	✓ 87.00	
\$ 2054.80	2,519.00	BR✓
\$ 342.50	416.00	CUT✓
\$	✓ 35.00	DL✓
\$	851.00	NDX
\$	✓ 56.00	} NECV
\$	✓ 56.00	
\$	156.00	NDX
\$	✓ 210.50	SCV
\$	210.50	NDX
\$	✓ 48.00	NECV
\$	1,884.00	} NDX
\$	48.00	

	3062.95	\$	6,781.00
@5%	153.15	-5%	\$ 1,695.25
	2909.80		\$ 5,085.75

Qty Spare Parts

- 1set Rear bumper clips

Special Nett (\$)

\$ 30.00	80.00	NECV
----------	------------------	------

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 400.00	800.00	✓
-----------	-------------------	---

Spray painting on affected panels

\$ 400.00	800.00	✓
-----------	-------------------	---

Check wiring and lighting system

\$ 300.00	100.00	X NN
----------------------	-------------------	------

Apply rust coating on affected areas

\$	80.00	NNX
----	------------------	-----

Remove and replace rear inner trims and garnish to assist repairs

\$	250.00	NNX
----	-------------------	-----



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT,
SINGAPORE 415875

Estimate for SJX93L (Audi A6)

Supplementary

Qty Spare Parts

1 Bootlid

2455.12
@ 5% 122.76
2332.36

2014
List Price (\$)

\$ 3,219.00 DDV ✓
2455.12
\$ 3,219.00
-5% \$ 160.95
\$ 3,058.05

Qty Spare Parts

1set Bootlid inner trim clips

Special Nett (\$)

\$ 30 ~~50.00~~ NUX

Total:

\$ 3,118.05

Remove and replace rear bumper reverse sensors and wire harness to assist repairs

\$ 60.00 ~~80.00~~

Remove and replace rear RH exhaust silencer

\$ ~~150.00~~

\$ 7,425.75

860.00

Survey
7/4/2021
Tulim lin
1100hrs

No Necessary for
resurvey.
Damages are external

Lump sum repair
Repair days 4

PARTS 5242.17

SN 30.00

LABOUR 860.00

6132.17

@ 20% 1226.43

4905.73

L/s 4,900/2

Tulim lin
17/4/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: