

08/11/13) wef  
ASS. REC. BY: Rame

REF: CC4/LPC21004335/R1ba3

724F

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV

To Inspect Vehicle No: SMK 9117

at Workshop m/s. TRANSBULO KMS

of 21A, Panyam Panyam

Insured: LPC

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 91K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMK 9117 Yr Regn: 2019 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 6 SEDAN 2.0 AT EX C.C. 1998

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 46887 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 5M69L1072K0311879

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: \_\_\_\_\_

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/03/21 D.O.I. 06/04/21

Survey held at TRANSBULO KMS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S & O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 45K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ S + RS, SI

☐ : Interview (\$ \_\_\_\_\_)

Photos

☐ : Tech. Invs (\$ \_\_\_\_\_)

Others

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

## ESTIMATE COST OF REPAIRS

## LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

NAME :

ADDRESS :

TEL :

WIP :

31820

EXCESS :

DATE :

6-Apr-21

ATTN. :

FAX :

VEH NO :	SMK911J	DATE IN :		CONTACT PERSON :	EVA
CHASSIS NO :	JM6GL1072K0311879	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	MAZDA6	DATE REG :	26-Mar-19	POLICY NO. :	

## NATURE OF WORKS

## Parts Description

1	FRONT BUMPER <i>de /</i>	MGSJ8-50-031 BB	1			-	1,211.90
2	GROMMET, SCREW <i>ne /</i>	MGHP9-50-0Z5	2			-	5.80
3	RETAINER LHF BUMPER <i>ne /</i>	MGHP9-50-0U1C	1			-	14.70
4	RETAINER RHF BUMPER <i>de /</i>	MGHP9-50-0T1B	1			-	17.10
5	COVER(L), BUMPER (INSIDE) ?	MGSJ7-50-104	1			-	30.20
6	COVER(R), BUMPER (INSIDE) ?	MGSJ7-50-103	1			-	30.20
7	RIVET <i>ne /</i>	MS51S-51-833	8			-	32.00
8	PLATE(L), SEAL-F. BUMPER ?	MGSJ7-50-1V0	1			-	78.90
9	PLATE(R), SEAL-F. BUMPER ?	MGSJ7-50-1U0	1			-	78.90
10	RIVET <i>ne /</i>	MBBM4-50-355	4			-	18.00
11	FOGLAMP GARNISH LH ?	MGBVG-50-131	1			-	65.80
12	FOGLAMP GARNISH RH <i>X</i>	MGBVG-50-121	1			-	65.80
13	FOGLAMP BASE GARNISH LH ?	MGSJ7-50-102	1			-	20.50
14	LOWER GRILLE CAP LH <i>X</i>	MGSJ7-50-M42	1			-	60.50
15	LOWER GRILLE CAP RH <i>X</i>	MGSJ7-50-M32	1			-	60.50
16	FOGLAMP BASE GARNISH RH <i>X</i>	MGSJ7-50-101	1			-	20.50
17	STIFF'A', BUMPER GL3 <i>X</i>	MGRF2-50-0S0A	1			-	99.80
18	FRONT BUMPER SPONGE <i>cm /</i>	MG48F-50-111	1			-	60.60
19	CLIP FOR BUMPER SPONGE <i>ne /</i>	MFD01-68-AC3	2			-	12.40
20	REINF., FRT BUMPER GL3 <i>bt /</i>	MGSJ7-50-070	1			-	579.90
21	FRONT BUMPER SENSOR <i>sc /</i>	MKD47-67-UC1 PR	1			-	361.60
22	GRILLE TOP <i>sc /</i>	MGSJ7-50-7E1 PR	1			-	453.80
23	RIVET FOR GRILLE TOP <i>ne /</i>	MTK21-50-355	6			-	55.20
24	GRILLE TOP BRACKET RH <i>X</i>	MGSJ7-50-153	1			-	14.50
25	GRILLE TOP BRACKET LH <i>cm /</i>	MGSJ7-50-163	1			-	14.50
26	RIVET (NEC) <i>ne /</i>	MS51S-51-833	8			-	32.00
27	SUPPORT TOP COVER <i>cm /</i>	MGHR1-50-1A1	1			-	46.50
28	FRONT SUPPORT PANEL TOP BRACKET <i>bt / ?</i>	MGSJ7-50-717A	1			-	95.00
29	FASTENER FOR SUPPORT BRACKET <i>ne /</i>	MGD7A-50-EA1	4			-	12.80
30	FRONT BUMPER BRACKET LOWER RH <i>X</i>	MGSJ7-50-151	1			-	37.10

FRONT BUMPER BRACKET LOWER LH ?	MGSH7-50-161	1			-	37.10
BRACKET(L),F. BUMPER SIDE GL3 ne/	MGSH7-50-162	1			-	37.10
BRACKET RHF BUMPER SIDE GL3 nec/	MGSH7-50-152	1			-	37.10
PIN,LOCATOR ne/	MKD45-50-1K5A	2			-	5.80
FRONT GRILLE BASE cm/	MGSH7-50-712B	1			-	133.70
FRONT GRILLE MESH cm/	MGSH7-50-719	1			-	180.40
CLIP (NEC) ne/	MGSH7-50-EB1	1			-	9.10
FRONT GRILLE CHROME GARNISH LH cm/	MGSH7-50-7K0D	1			-	251.40
FRONT GRILLE CHROME GARNISH RH ?	MGSH7-50-7J0D	1			-	251.40
FRONT GRILLE LOGO nec/	MG46L-51-730	1			-	55.50
BRACKET,RAD.GRILLE LOGO cm/	MGBFN-50-716	1			-	106.50
WIPER GARNISH RH de/	MGBEF-51-PB1	1			-	15.50
WIPER GARNISH LH +	MGBEF-51-PC1	1			-	15.50
BONNET bt/	MGBY0-52-31XB	1			-	1,264.60
INSULATOR,BONNET X	MGBFN-56-681A	1			-	189.00
HINGE(L),BONNET bt/	MGBFT-52-420E	1			-	118.10
HINGE(R),BONNET bt/	MGBFT-52-410E	1			-	114.40
TAPE,PROTECTOR-STOPP nec/	MC001-56-864A	2			-	10.80
WTHSTP,PARTING SEAL X	MGHP9-56-770	1			-	104.10
WTHSTP,BONNET-FRT cut/	MGHP9-56-750	1			-	32.90
LOCK,BONNET ?	MGBGA-56-620A	1			-	186.20
FRONT SUPPORT TOP PANEL ? bt/	MGSH7-53-150	1			-	121.40
STAY,LOCK ?	MGHP9-52-15YA	1			-	43.10
SUPPORT PANEL cm/ photo?	MGHP9-53-110B	1			-	418.10
GRILLE UNDER X	MGSH7-50-R10	1			-	764.40
SUPPORT PANEL SUPPORT ?	MGSH7-50-1C0B	1			-	156.90
FASTENER ne/	MGD7A-50-EA1	4			-	12.80
FENDER RHF bt/	MGHP9-52-111A	1			-	383.70
FENDER LHF bt/	MGHP9-52-211A	1			-	383.70
GUARD RHF MUD de/	MGRF2-56-130	1			-	114.30
GUARD LHF MUD de/	MGRF2-56-140	1			-	114.30
STAY(L),FENDER ?	MGHP9-52-240D	1			-	48.30
STAY(R),FENDER ?	MGHZ9-52-1R0A	1			-	48.30
UNDERSHIELD CLIPS nec/	MB45A-56-146A	20			-	60.00
FASTENER CLIPS ne/	MGJ21-68-885B02	6			-	18.00
FRONT DOOR OUTER MOULDING RH cut/	MGHP9-50-640F	1			-	96.00
GARNISH RHR DOOR C-PILLAR ? ne/	MGJR9-50-M50A	1			-	54.60
GARNISH RHR DOOR B-PILLAR ? ne/	MGBFT-50-M30	1			-	116.10
GARNISH(R),RHF DOOR (PIANO BLACK) nec/	MGBFT-50-M10	1			-	99.20
STRIPE NO.1(R), BODY SIDE ne/	MGRT6-50-8V1A00	1			-	11.00
STRIPE NO.3(R), BODY SIDE ne/	MGRT6-50-8V3A00	1			-	12.90
STRIPE NO.2(R),BODY SIDE nec/	MGRT6-50-8V2A00	1			-	11.90
STRIPE UPPER RHR DR ne/	MGRT6-50-8V4A00	1			-	15.50
FRONT DOOR RH bt/	MGHY0-58-02XJ	1			-	975.20
HINGE(R),DOOR-UPPER DJ/KE/KG ?	MKD53-58-210A	1			-	37.40
HINGE'B',DR-LHF LWR DJ/BP/DM ?	MD461-59-210B	1			-	37.80
WEATHERSTRIP RHF DR GL3 ne/	MGBFN-58-760	1			-	90.60

80	FRONT DOOR GLASS RH <i>ca /</i>	MGRT6-58-510B	1			-	471.10
81	FRONT DOOR RUN CHANNEL RH <i>?</i>	MGRT6-58-605A	1			-	140.90
82	FRONT DOOR HANDLE <i>scr /</i>	MTK49-58-41XCPR	1			-	212.50
83	FRONT DOOR HANDLE CAP <i>x</i>	MD09L-58-415BPR	1			-	24.70
84	FRONT DOOR HANDLE UNDERLAY <i>+</i>	MKD53-58-414	1			-	5.70
85	FRONT DOOR HANDLE BASE RH <i>?</i>	MGHP9-58-42XD	1			-	77.00
86	SEAT(L),HANDLE-OUT GL/KG <i>?</i>	MKD53-59-414	1			-	5.70
87	FRONT DOOR LOCK RH <i>?</i>	MGW0H-58-310A	1			-	216.70
88	CARRIER(FRT,R),DOOR <i>?</i>	MGBJD-58-97X	1			-	116.30
89	MOTOR(R),WINDOW <i>?</i>	MD651-58-58XB	1			-	166.70
90	PLUG,HOLE (NEC) <i>nee /</i>	MF151-58-866	4			-	13.60
91	ARM/BASE RHF WINDOW <i>?</i>	MGHP9-58-590A	1			-	133.10
92	CHECKER,FRT DR <i>?</i>	MGBFN-58-270	2			-	94.40
93	COVER,HOLE (NEC) <i>nee /</i>	MGHP9-58-972	2			-	10.40
94	FRONT DOOR RH INNER TRIM <i>?</i>	MGCCD-68-420E02	1			-	2,427.50
95	FASTENER CLIP FOR TRIM <i>nee /</i>	MGJ6A-68-AB1	18			-	129.60
96	FASTENER CLIPS <i>nee /</i>	MGE4T-68-865A	2			-	4.80
97	REAR DOOR RH <i>bf /</i>	MGHY1-72-02XB	1			-	1,312.10
98	HINGE'B'RHR DR SKYACTIV <i>?</i>	MKD53-72-240A	1			-	44.80
99	MKD53-72-210A/HINGE'B'LHR DR SKYACTIV <i>?</i>	MKD53-72-210	1			-	48.30
100	WEATHERSTRIP RHR DOOR <i>x</i>	MGBFN-72-760	1			-	143.10
101	REAR DOOR RH OUTER HAND;E <i>scr /</i>	MTK48-58-41XBPR	1			-	78.90
102	REAR DOOR HANDLE CAP <i>repair</i>	MD09W-58-415BPR	1			-	22.30
103	REAR DOOR HANDLE UNDERLAY <i>?</i>	MKD53-58-414	1			-	5.70
104	REAR DOOR HANDLE BASE <i>?</i>	MGHP9-72-42XB	1			-	59.60
105	CHECKER RH,REAR DOOR <i>?</i>	MGBFN-72-270	2			-	113.80
106	LOCK RHR DR <i>?</i>	MGJT1-72-310A	1			-	234.20
107	STRIKER DR <i>x</i>	MGS1D-58-361A	2			-	54.40
108	MOTOR(R),WINDOW <i>?</i>	MD651-58-58XB	1			-	166.70
109	PLUG,HOLE (NEC) <i>ne /</i>	MF151-58-866	2			-	6.80
110	CARRIER RHR DOOR GL <i>?</i>	MGHP9-72-97XB	1			-	96.20
111	COVER RHR,HOLE-DOOR IN <i>?</i>	MG46G-72-973	1			-	35.70
112	REAR FENDER RH <i>bf /</i>	MGSY7-70-41X	1			-	1,312.50
113	SIDE MIRROR RH <i>bro /</i>	MGSB9-69-121A	1			-	475.90
114	SIDE MIRROR BASE GASKET <i>ne /</i>	MGHP9-69-115	1			-	13.30
115	SIE MIRROR GLASS <i>bro /</i>	MB63C-69-1G1	1			-	282.50
116	SIDE MIRROR LIGHT RH <i>bro /</i>	MB63B-69-122A	1			-	85.80
117	SCREW,DOOR MIRROR <i>ne /</i>	ML208-69-126	6			-	108.00
118	SIDE MIRROR COVER HOUSING <i>mis /</i>	MB63B-69-1N1 PR	1			-	128.40
119	CAP,ASSIST HANDLE <i>?</i> <i>scr /</i>	MGAL1-69-472A75	8			-	80.00
120	WHEEL,DISC 17"X7 GL <i>scr /</i>	M9965-16-7570	2			-	2,393.60
121	VALVE,AIR <i>ne /</i>	M9963-60-4140	2			-	13.40
122	CAP,CENTER RIM BM/BN/BP <i>x</i>	MKD51-37-190	2			-	43.20
123	FRONT SHOCK ABSORBER RH <i>?</i>	MGBJD-34-700A	1			-	392.40
124	RUBBER,SPRING SEAT <i>?</i>	MKA0G-34-0A3	2			-	46.80
125	STOPPER,BUMPER GL <i>?</i>	MGBFN-34-111	2			-	58.20
126	BEARING,FRONT STRUT <i>?</i>	MB45A-34-38XA	2			-	111.60

SHOCK ABSORBER MOUNTING ?	MKD35-34-380C	2			-	193.00
LOWER ARM RH ?	MG46C-34-300J	1			-	503.90
KNUCKLE ARM RH ?	MGBFN-33-021	1			-	378.10
WHEEL HUB W/ BEARING ?	MKD35-33-04XF	2			-	1,133.40
		0			-	-
		0			-	-
TOTAL PARTS						25,516.00
TOTAL PARTS COST						25,516.00

1	TO REMOVE & REPLACE THE, BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE MIRROR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT & ALL ACCIDENT DAMAGE AREAS. TO REPAIR A-PILLAR RH & ALL AREAS AFFECTED BY THE ACCIDENT	6600	8,250.00
2	TO RESPRAY BONNET, FRT BUMPER, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE MIRROR COVER RH, A- PILLAR RH	5040	5,985.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	280	350.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	150	250.00
5	TO REMOVE & REPLACE RADIATOR & CONDENSER TO GIVE WAY ON THE REPLACEMENT OF FRONT SUPPORT PANEL	330	660.00
6	TO TOP UP AIRCON GAS,	NETT 180	280.00
7	TO REMOVE & REPLACE FRONT UNDERCARRIAGE RH	660?	990.00
8	TO REPLACE/ SUPPLY 4PC OF TYRE 225/55 R17 (1pc)	NETT 450	1,800.00
9	TO MOUNT 2PCS OF RIMS & CONDUCT WHEEL BALANCING	NETT	240.00
10	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT	NETT	560.00
11	TO TRANSFER THE FRONT DOOR & REAR DOOR MECHANISM	NETT	660.00
12	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS	NETT	560.00
13	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS	NETT	120.00
14	TO REPLACE THE FRONT DOOR GLASS	150-	350.00
15	TO SUPPLY SOLAR FILM ON THE FRONT DOOR GLASS (inmate)	NETT	140.00

18	TO TRANSFER THE FRONT BUMPER SENSORS	150	300.00
19	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	NETT 180	250.00
20	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	NETT 250	350.00
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP (insurance)	-	? 200.00
	SUNDRIES	-	20 280.00

TOTAL LABOUR	14,585.00
TOTAL PARTS	25,516.00
TOTAL	40,101.00
LESS EXCESS	-
TOTAL AFTER EXCESS	40,101.00
GST 7%	2,807.07
GRAND TOTAL	42,908.07

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

### SUPPLEMENTARY PARTS

Date:

1	0	0	0	-
2	0	0	0	-

TOTAL PARTS

TOTAL PARTS COST

1	#N/A	Rasul Hp 92010066	-
2	#N/A	16 days 06/04/21 @ 1545	-

Rasul after repair

SUPPLEMENT LABOUR	-	-
SUPPLEMENT PARTS	-	-
TOTAL SUPPLEMENT	-	-
	-	-
	-	-
GST 7%	-	-
GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission .....  
Date of Accident ..... 31/03/2021 16:55 (SGT)  
Exact Location of Accident ..... 30/03/2021 07:15 (SGT)  
Additional Location Information ..... Punggol Flyover, Singapore  
Country/State of Loss ..... -  
Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMK911J

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... Koh Sheng Chiang  
NRIC No ..... S8007724F  
Email Address ..... NOEMAIL@AIG.COM  
Mobile Phone No ..... (Phone) +65-98896890  
Alternative Phone No ..... +65-98428026

### VEHICLE PARTICULARS

Manufacturer ..... Mazda  
Model ..... 6  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident .....  
Are you claiming under your own insurance policy for repair to your vehicle? .....  
Vehicle Category ..... No - Reporting only  
Transmission ..... Private car  
CC ..... Auto  
1998

### INSURANCE COMPANY

Name of Insurance Company ..... AIG Asia Pacific Insurance Pte. Ltd.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 1900084793-01  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... Koh Sheng Chiang  
NRIC No ..... S8007724F

Date Of Birth	22/03/1980
Occupation	Indoor
Date Of Driving Pass	12/02/2004
Driving experience	17 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-98896890
Alt. Phone Number	+65-98428026
Email Address	NOEMAIL@AIG.COM
Address	267B PUNGGOL FIELD
Address complement	#05-119 SINGAPORE
Postcode	822267
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Sengkang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18003438999
Alt. Police Station Phone No	(Fax) +65-63438939
Police Station Address	2 Sengkang Square #01-02
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

On 30 March 2021 at around 7.15am I am driving my car SMK911J. I am going from punggol way going straight towards punggol flyover facing tampines direction. I am in the centre lane of a 3 lane road. I am going straight with no intention of changing lanes. While driving straight I felt a strong impact on the right rear of my car. I glance and realised I was hit by a big lorry XD5915Y. The collision caused by car to spin 180 degrees in front of the lorry. After being push for some distance

both our vehicle stopped moving. My car is now on the right side of the lorry instead of the left side as I originally was and is now facing against the traffic. My driver side door was crush and stuck and the door windows were also broken. I can only get out of the car thru the passenger side. The roadside railing were also slightly damage. No pedestrian or other road user were involved in the accident. Lucky there is a LTA officer nearby and he assisted me to get out of my car before diverting traffic. The traffic police and ambulance were alerted. After getting out of my car

I managed to get the work permit and license details from the lorry driver and take some photo of the accident. I went back to sit in the passenger seat as I am no able to stand properly. Shortly the ambulance came and I was send to Sengkang hospital accident and emergency. I feel my left body in pain and numbness. The doctor prescribed strong pain killers and muscle relaxant to relief the pain. I was given 5 days MC. Police report has been made.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

Was there any video captured by Car Camera? .....  
Reasons for not uploading a video of the accident .....  
Was there any audio recorded? .....

Yes  
NO VIDEO UPLOADED  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... XD5915Y  
Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Commercial vehicle  
Name of Driver ..... -  
Contact Number ..... -  
Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person ..... -  
Address ..... -  
Address Complement ..... -  
Post Code ..... -  
Approximate Age Years Old ..... -  
Injuries Sustained ..... -  
Injured person in which vehicle? ..... -  
Were seat belts worn? ..... -  
Was this injured conveyed to hospital by ambulance? ..... -



# SINGAPORE POLICE FORCE



T/20210330/2044

Police Station Of Origin:

Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE  
545025

Tel No: 1800-343 8999

1 of 4

Report No. T/20210330/2044

**REPORT OF A TRAFFIC ACCIDENT**Date/Time Report Made:  
30/03/2021 12:02

Vide Report No.:

Station Diary No.:  
36**Informant's Particulars**Name of Informant:  
KOH SHENG CHIANG, CARTERAddress:  
APT BLK 267B PUNGGOL FIELD #05-119 SINGAPORE  
822267ID Type / ID No.:  
NRIC NO / S8007724FContact No.:  
Home/Office: Mobile: 98896890Nationality:  
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:  
Male 41 22/03/1980Type of Informant:  
DriverRace:  
Chinese

Language:

Institution / School Name:

Occupation:  
ENGINEERINGDriving Licence Information:  
Class: 2B,2A,3 Date of Expiry:**General Information of the Accident**Type of  
Accident:Injury  
Conveyed By AmbulanceDrink  
Drive:  
NoDate/Time of  
Accident:  
30/03/2021 07:15Type of Location:  
Straight Road

Location:

PUNGGOL WAY

Weather:  
ClearRoad Surface:  
Dry

Road Speed Limit:

Traffic Flow:  
One Way

Traffic Control:

Traffic Volume:  
HeavyType of Collision:  
Between Moving Vehicles - Side Swipe - Same DirectionAnyone conveyed by  
ambulance:  
No**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMK911J	Car	MAZDA	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD	Red	Seriously Damaged	0
XD5915Y	Lorry				Slightly Damaged	2



Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMK911J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900084793-01	26/03/2021	25/03/2022

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	KOH SHENG CHIANG, CARTER		ID No.	S8007724F
Related Vehicle	SMK911J (Car)		Contact No.	98896890
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	30/03/2021		Date Discharge	30/03/2021
No. of Days granted Medical Leave	05		Degree of Injury	Slight
Driver				
Name	CHINNASAMY PRKASH		ID No.	G6763151Q
Related Vehicle	XD5915Y (Lorry)		Contact No.	94557362
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 30/3/2021 at 0715hrs, I was driving my car, SMK911J, and I just made a turn from Punggol Way and going towards TPE, Punggol flyover. The road has 3 lanes and I was in the middle lane. I was going straight and had no intention of changing lanes. Subsequently while driving, I felt a strong collision on the rear right side of my car. I then saw from the side mirror that a big lorry, XD5915Y, has collided with my car.

The collision then caused my car to turn 180 degrees and made my car face against the flow of traffic. My car was also now switched to the right side of the lorry instead of the left side as it originally was and my driver door was blocked by the front of the lorry. After the impact, both our vehicles stopped moving. There was a LTA officer nearby and he assisted me to get out of my car from the passenger side door. After getting out of my car, I then managed to talk to the driver of the lorry and we both exchanged contact information. Shortly after that, the ambulance came and conveyed me to Sengkang General Hospital.



**SINGAPORE  
POLICE FORCE**



T/20210330/2044

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

3 of 4

Report No. T/20210330/2044

**CONTINUATION OF REPORT**

I am feeling a lot of discomfort on my whole left side of my body. I was given 5 days MC after consultation with the doctor.

The side railings on the road was slightly scratched due to the accident. No other pedestrians were involved in the accident.



# SINGAPORE POLICE FORCE



T/20210330/2044

Police Station Of Origin:  
Sengkang N.P.C  
2 Sengkang Square #01-02 SINGAPORE  
545025  
Tel No: 1800-343 8999

4 of 4

Report No. T/20210330/2044

## CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Sgt 2 MUHAMMAD SUHAIRI BIN MOHD  
HAMZAH

Signature Of Interpreter:  
Not applicable


Officer In Charge Of Case:  
TP / GIT /  
Sgt 2 DAVID YAP  
Contact No.: 96192349

Signature Of Informant:

Date/Time:  
30/03/2021 12:02

Classification Of Case:

Authentication Stamp  
NP168



NP168

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	724F
Vehicle No.:	SMK911J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Apr 2021
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	PE21255840
Chassis No.:	JM6GL1072K0311879
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$22,728.00
Original Registration Date:	26 Mar 2019
First Registration Date:	26 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$23,820.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2029
PARF Rebate Amount:	\$17,865.00
COE Expiry Date:	25 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$27,486.00
<b>Total Rebate Amount:</b>	<b>\$45,351.00</b>

The information contained herein is correct as at 07 Apr 2021

OK

# Mazda 6 2.0A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$91,413****Depreciation** ?

\$10,290 /yr

[View models with similar depre](#)**Reg Date**

29-Mar-2019

(7yrs 11mths 21days COE left)

**Mileage**

18,000 km (8.9k /yr)

**Manufactured** ?

2019

**Road Tax** ?

\$1,210 /yr

**Transmission**

Auto

**Dereg Value** ?

\$41,442 as of today (change)

**OMV** ?

\$18,603

**COE** ?

\$35,310

**ARF** ?

\$18,603

**Engine Cap**

1,998 cc

**Power**

121.0 kW (162 bhp)

**Curb Weight** ?

1,515 kg

**No. of Owners** ?

2

**Type of Vehicle**

Luxury Sedan

## Features

[View specs of the Mazda 6 Sedan \(2018\)](#)

## Accessories

19 Inch New Rims And Tyre Changed In March 2021. Tuff Kote And System 6 Treatment. Car Video Recorder. V KOOL Solar Films.

## Description

Warranty By Mazda Till March 2022. Lady Owner. Use To Fetch Kids Only. Brand New Tyre And 19 Inch Rims Changed On 12th March 2021. Super Well Kept. Just Done Servicing At Mazda On 15th March 2021 At 17500km. All Servicing Done Since Day 1 With Mazda Record Book. Careful And Detail Owner, 2 Years Change Sport Rims Once. Rejected 86k Offer From Dealer. Any Lower No Need Try. Thank You.

## Category

PARF Car, Direct Owner Sale, Low Mileage Car

## Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

## Resources



### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



### Car Valuation - Free

Find out the market value of your existing car for free. Get started


Posted on: 05-Apr-2021

[Compare](#)[History](#)

**100% FREE**  
PAPERWORK  
SUPPORT FOR  
BOTH BUYER  
& SELLER

Preferred

## Price Chart



Click on the point to v

Shortlist

More

## Seller Information

Contact Person(s)

Contact No.

Enquiry