



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105186

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 26/07/2021
Reference CC4/FCI21004336/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKT 8128C
Insured Veh. GBE 9983D
Claim No. D21001056MFCV/1
Policy No. D-20095634MFCV
Accident Date 03/04/2021
Inspection Date 07/04/2021

Description	Total
Survey Inspection	429.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	429.00
GST (7%)	30.03
Grand Total	459.03

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21004336/R1ra3q2 Date: 26/07/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 9983D	Veh. Inspected	SKT 8128C	
Policy No.	D-20095634MFCV	Coverage (\$)	0.00	
Claim No.	D21001056MFCV/1	Excess (\$)	0.00	
Assign From		Assign Date	06/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER DISCOVERY SPORT 2.0P	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	SALCA2AX5MH887645	Colour	GREY	
Odometer	001571 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R20	PIRELLI	6 mm	
L/H Front Tyre	235/50 R20	PIRELLI	6 mm	
R/H Rear Tyre	235/50 R20	PIRELLI	6 mm	
L/H Rear Tyre	235/50 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2021	Inspection Date	07/04/2021	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8128C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE -LESS HING (SN)	DEFORMED	3,290.90	2,961.81
1	GLASS -BACK WINDOW (SN)	NECESSARY	1,073.10	965.79
1	*D* PRIMER GLASS & P (SN)	NECESSARY	43.30	38.97
2	ADHESIVE AND SEALER (SN)	NECESSARY	319.00	287.10
1	LOGO REAR "DISCO" BL (SN)	NECESSARY	154.20	138.78
1	LOGO REAR "VERY"BLA (SN)	NECESSARY	154.20	138.78
1	BADGE OVAL REAR RR3 (SN)	NECESSARY	91.50	82.35
1	LATCH-TAILGATE (SN)	NOT NECESSARY	277.60	-
1	BUMPER -REAR (SN)	NOT NECESSARY	2,008.20	-
1	BUMPER -COVER LOWER (SN)	NOT NECESSARY	626.00	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	73.90	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	73.90	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	124.60	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	124.60	-
1	FINISHER -BUMPER RH (SN)	NOT NECESSARY	217.80	-
1	FINISHER -BUMPER LH (SN)	NOT NECESSARY	218.10	-
1	LAMP -FOG -REAR RH (SN)	NOT NECESSARY	364.50	-
1	LAMP -FOG -REAR LH (SN)	NOT NECESSARY	364.50	-
4	SENSOR -PARKING AID (SN)	NOT NECESSARY	974.00	-
1	ADHESIVE SEALER FL2 (SN)	NOT NECESSARY	709.60	-
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	955.20	-
			12,238.70	4,613.58
	<u>LABOUR</u>			
	TO REPLACE TAILGATE ,REAR BUMPER ,ETC.		2,800.00	1,000.00
	TO SPRAY TAILGATE ,REAR BUMPER .		2,500.00	1,000.00
	TO REPLACE REAR WINDSCREEN .		600.00	600.00
	TO INSTALL REAR WINDSCREEN FILM.		280.00	280.00
	TO REMOVE & REFIT ,TRANSFER TAILGATE INTERIOR PARTS.		500.00	500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	621.00
			7,301.00	4,001.00
GRAND TOTAL			19,539.70	8,614.58
RECOMMENDED COST OF REPAIRS				8,614.58

Report Ref No. CC4/FCI21004336/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 8128C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 8128C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

