

CHIA'S VEGETABLES TRADING
2A BRIDPORT AVENUE
SINGAPORE 559394

File No : SH/2021/050/04/003/TP
Date : 27-April-2021

*Not Authorized
L1 Rep @ 1900hr*

4 days

Estimated cost of repair for vehicle no : **GBK5716D** Model **KIA K2500**
Accident involving vehicle no: **GBK5716D** & **SMP4092U** on **01.04.2021**

Description	Quantity	Cost Price
Front bumper	1	\$ <i>Not/Car</i> 385.00 ✓
LH Front bumper retainer	1	\$ <i>Sn</i> 45.00 X
LH head lamp	1	\$ <i>Car</i> 365.00 ✓
LH front corner panel	1	\$ <i>Ry</i> 147.00 ✓
LH front door	1	\$ <i>R1</i> 764.00 ✓
LH front door signal lamp	1	\$ <i>Bru</i> 45.00 ✓
LH front door hinge top	1	\$ <i>R</i> 55.00 X
LH front door hinge bottom	1	\$ <i>R</i> 55.00 X
LH front door 'K2500' sticker	1	\$ <i>Mu</i> 48.00 ✓
		\$ 1,909.00
	Less 10%	\$ 190.90
		\$ 1,718.10

LH front door company sticker 1 SN \$ *Mu* 25.00 ✓

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp. \$ 25.00 *20cl*

To remove damaged parts, to jack out front support panel, front body and cut out damaged parts, to reweld , reshape and repair LH front corner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment. \$ 420.00 *40cl*

To spray paint LH front door , LH front corner panel, and inner damaged portion inclusive of preparatory works and material. \$ 450.00 *36cl*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

2,638.10

T/Party: AIG Asia Pacific Insurance Pte Ltd