



Tax Invoice No.:	AR202105-0040
------------------	---------------

CHIA'S VEGETABLES TRADING  
NO. 2A  
BRIDPORT AVE  
SINGAPORE 559394

File No : SH/2021/030/04/003/TP  
Date : 19-May-2021

Cost of repair for vehicle no: GBK5716D KIA K2500 6MT  
Accident involving vehicle no: GBK5716D & SMP4092U on 01-April-2021

**Description**

To Supply Spare Parts

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.  
To remove damaged parts, to jack o ut front support panel, front body and cut out damaged parts, to reweld , reshape ,and repair LH formt corner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment.  
To spray paint LH front door, LH front corner panel, and inner damaged portion inclusive of preparatory works and material.

Lump Sum Cost of Repair \$	1,900.00
7% GST \$	133.00
<b>\$</b>	<b>2,033.00</b>

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

**Received By**

No signature is required as this is a computer generated invoice