

和 好 贸 易

HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 539187, Tel: 62844487 Fax: 62898180

Dear Sir,

Estimate cost repair for the accident motorcycle Vehicle No: FBQ9739E

Items	Price
Front Fork 1 Set	\$820 <i>buy/cne /</i>
Headlight 1 Set	\$286 <i>cne /</i>
Left Signal Light	\$65 <i>cne /</i>
Top Cowling 1 Set	\$250 <i>cne /</i>
Inter Panel Center	\$192 <i>cne /</i>
Left Foot Panel	\$105 <i>D.S /</i>
Outer Panel	\$192 <i>D.S /</i>
Rear Left Side Box	\$200 <i>rx</i>
Left Side Body Bracket	\$85 <i>rx</i>
Front Fender	\$98 <i>45 /</i>
Under Bracket	\$380 <i>?</i>
Labour Charge	\$300 <i>280</i>
Total	\$2973

1102

not Authorised

Wah
mercans

7/4/21

Whisper Attorney

3 days

MP: 90096608

2/2/21

HA

HUA HO TRADING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Its prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: