



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr Ragupathy S/O Narayanamoorth Reg No/Reg Date SMQ3525P / 12/11/201 Date In/Mileage / 0 Chassis No GF7W0601993 Engine No 4J11BH5944 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/03/2021/ 11:36	TLE	261 / Edwin Caina	64115			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								530 1350.00
RENEW RR BUMPER & BODY KIT			1 + 80 x 450					
REPAIR LHR FENDER								350 1310.00
E PNT98000								30.00
RESPRAY RR BUMPER, RR BUMPER BODY KIT & LHR FENDER			1 x 350					120.00
A 54900099								
CHECK WIRING ELECTRICAL								60.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								1554.00
M SUNDRY								1243.20
Sundries					1.00	1554.00	20.00	624.47
M BODY KIT, OUTLANDER					1.00	811.00	23.00	9.24
M FACE, RR BUMPER					1.00	12.00	23.00	12.32
M BRKT, R/BMPR FACE SIDE, LH					8.00	2.00	23.00	60.83
M CLIP, ENG ROOM COVER					1.00	79.00	23.00	277.20
M REINFORCEMENT, RR BUMPER, LH					1.00	360.00	23.00	464.31
M EXTENSION, RR BUMPER					1.00	603.00	23.00	77.00
M LAMP ASSY, COMB, RR LH					1.00	100.00	23.00	81.62
M REFLECTOR, TAIL LAMP, LH					1.00	106.00	23.00	123.20
M MOULDING, RR BUMPER, LH					1.00	160.00	23.00	
M MOULDING, RR WHEEL ARCH, LH								

Estimate

Steve CLKK

6/4/21, 1.30pm

Wil Pro

SURVEYOR NAME: Steve (LKK) 6/4/21, 1.30pm
SURVEYOR SIGNATURE: Wil Perle
DATE: PIP
REMARKS: My Bel Spy

Confirm & accepted by is hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

3 days
7% GST on 5863.39
Total Payable 6,273.83

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.