

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

LEAH HSIAO TUNG

Not Authorized
leah

6/4/21

2/5 @ 27,000
12 days.

VEHICLE No: SMM 6599C

1PC	REAR BUMPER	Dis	2012.32	\$2,455.10	/
1PC	REAR BUMPER PDC SENSOR O/S	Should	215.00	\$265.00	/
1PC	REAR BUMPER REINFORCEMENT	11		\$815.00	X
1SET	REAR BUMPER CLIPS & RIVET	nee		\$60.00	/
1PC	REAR BUMPER SIDE HOLDER O/S	Bent	125.00	\$166.20	/
1PC	REAR TAILLAMP O/S	11		\$1,028.00	X
1PC	REAR WINDSCREEN	11		\$1,281.10	X
1SET	REAR WINDSCREEN REPAIR KIT	nee	175.00	\$211.00	/
1PC	REAR WINDSCREEN SEALANT	nee		\$60.00	40
1PC	REAR FENDER O/S	Scuffed	2628.21	\$3,228.20	/
1PC	REAR FENDER INNER TRIM O/S	11		\$645.10	X
1PC	REAR FENDER UNDER TRIM O/S	Scuffed		\$611.10	/
1SET	REAR FENDER UNDER TRIM CLIPS O/S	nee		\$50.00	/
1PC	REAR FUEL LIP	waged/cr		\$182.00	/
1PC	REAR SHOCK ABSORBER O/S	Bent	874.61	\$488.90	/
1PC	REAR KNUCKLE ARM O/S	Bent	1654	\$1,488.20	/
1PC	REAR WHEEL HUB BEARING O/S	Daged	470.99	\$850.00	/
1PC	REAR TORSION ARM O/S	twi	299.35	\$689.20	/
1PC	REAR TRUST ARM O/S	twi	285.11	\$455.20	/
1PC	REAR LOWER ARM O/S	Bent	715.43	\$918.90	/
1PC	REAR SPORT RIM O/S	Bent/waged	950.00	\$2,200.00	/
1PC	REAR DOOR O/S	Scuffed	2337.96	\$2,865.20	/
1PC	REAR DOOR INNER LOCK O/S	Should	650.00	\$845.20	/
1PC	REAR DOOR GLASS OUTER MOULDING O/S	nee	182.00	\$288.90	/
1PC	REAR DOOR GLASS OUTER TOP MOULDING O/S	nee	245.00	\$388.20	/
1PC	REAR DOOR GLASS REGULATOR & MOTOR O/S	Bent/Should	850	\$1,005.20	/
1PC	REAR DOOR INNER RUBBER O/S	nee	305.97	\$380.20	/
1PC	REAR DOOR INNER TRIM BOARD O/S	cre	1200.35	\$1,450.20	/
1SET	REAR DOOR INNER TRIM BOARD CLIPS O/S	nee		\$60.00	/
1PC	REAR DOOR OUTER HANDLE O/S	11		\$390.90	X
1PC	CENTRE PILLAR O/S	11		\$1,200.30	X
1PC	FRONT DOOR O/S	Scuffed	2655.12	\$3,120.90	/
1PC	FRONT DOOR INNER LOCK O/S	swc		\$669.20	X
1PC	FRONT DOOR INNER RUBBER O/S	nee	305.97	\$399.20	/
1PC	FRONT DOOR INNER TRIM BOARD O/S	Be/cre	1208.50	\$1,450.20	/
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S	nee		\$60.00	/
1PC	FRONT DOOR OUTER MOULDING O/S	nee	182	\$299.80	/
1PC	FRONT DOOR OUTER TOP MOULDING O/S	nee	255	\$388.20	/
1PC	FRONT DOOR GLASS REGULATOR & MOTOR O/S	11		\$1,241.50	X
1PC	FRONT DOOR MIRROR OUTER COVER O/S	cur	181.21	\$388.00	/
1PC	FRONT DOOR MIRROR SIGNAL LAMP O/S	scr	115.00	\$285.20	/
1PC	FRONT DOOR MIRROR ASSY O/S	Daged	1265.00	\$1,500.80	/

10%

1PC	FRONT DOOR INNER HANDLE BRACKET O/S	11	\$241.10	X
1PC	ROCKER PANEL GARNISH O/S	2el torn 652.35	\$820.20	
1PC	FRONT SHOCK ABSORBER O/S	11	\$455.80	X
1PC	FRONT KNUCKLE ARM O/S	Surf 1145.25	\$1,450.60	
1PC	FRONT KNUCKLE BEARING O/S	Dyed 450.50	\$650.00	
1PC	FRONT LOWER ARM O/S	11	\$911.20	X
1PC	FRONT SPORT RIM O/S	Surf 950.00	\$2,200.00	
1PC	FRONT FENDER O/S	Body 1102.35	\$1,520.20	
1PC	FRONT FENDER INNER SHIELD O/S	De 292.43	\$422.10	
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	all	\$50.00	
1PC	FRONT BUMPER	cut/torn 1965.21	\$2,248.90	
1PC	FRONT BUMPER SIDE RETAINER O/S	nn	\$165.00	X
1SET	FRONT BUMPER CLIPS	all	\$60.00	
1PC	FRONT REINFORCEMENT	Surf 615.00	\$815.20	
1PC	FRONT BUMPER SPONGE	Torn 188.20	\$249.20	
1PC	FRONT BUMPER PDC SENSOR O/S	should 215.00	\$255.00	
1PC	HEADLAMP O/S	one 3250.00	\$6,500.00	
1PC	FRONT SUPPORT PANEL	11	\$1,233.00	X
1PC	BONNET	R	\$2,945.20	X
1PC	AIR BAG CONTROL UNIT	sur	\$1,880.00	X
1PC	FRONT SAFETY BELT DRIVER	11	\$715.00	X
1PC	FRONT SAFETY BELT BUCKLE	11	\$450.00	X
1PC	REAR TYRE O/S	sur	\$300.00	X
			\$63,363.20	

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED PDC SENSOR	\$100.00	50
TO RESET & REPROGRAMME SYSTEM	\$280.00	200
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$300.00	120
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$300.00	150
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX FUEL TANK	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	100
TO DISMANTLE & REFIX BOTH DOOR MECHANISM	\$180.00	120
TO REFILL AIR CON GAS	\$120.00	X
TO SPRAY RUST PROOFING	\$180.00	120
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,000.00	1000
TO PUTTY & SPRAY PAINTING	\$2,500.00	1400
TOTAL	\$70,303.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3550
33791.98
102
30412.78
27170.