



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104464

INV Date 25/06/2021

Reference CC4/LPC21004353/Eba3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKD 251R
Insured Veh. GT 1234Y
Claim No. 21/21/21/VC05/024415
Policy No. Z21VC05006809
Accident Date 05/04/2021
Inspection Date 12/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21004353/Eba3q2 Date: 25/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 1234Y	Veh. Inspected	SKD 251R	
Policy No.	Z21VC05006809	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024415	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	06/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDC2533462F612024	Colour	BLUE	
Odometer	30092 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	PIRELLI	5 mm	
L/H Front Tyre	235/55 R19	PIRELLI	5 mm	
R/H Rear Tyre	235/55 R19	PIRELLI	5 mm	
L/H Rear Tyre	235/55 R19	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/04/2021	Inspection Date	12/04/2021	
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 251R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH/FRONT FENDER (SN)	DENTED	914.43	914.43
1	RH/COVER BUMPER AREA (SN)	CUT	229.67	229.67
1	FRONT BUMPER (SN)	TO REPAIR SEE LABOUR	1,964.91	-
1	RIVET (SN)	NECESSARY	48.10	48.10
			3,157.11	1,192.20
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		2,400.00	1,440.00
	RESPRAY RH/FRONT FENDER & FRONT BUMPER .		1,500.00	1,200.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	TO REMOVE ,CHECK HEADLAMP WITH FOCUS .		120.00	120.00
			4,400.00	3,140.00
	GRAND TOTAL		7,557.11	4,332.20
RECOMMENDED COST OF REPAIRS				4,332.20

Report Ref No. CC4/LPC21004353/Eba3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKD 251R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

