



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SKD251R

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

49331
SKD251R / 15/08/2019
WDC2533462F6120248
27492031761544
MB/MB GLC 250 4MATIC COUPE
028 890 Cavansite B/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WL001605	Credit	05/04/2021/ 19:33	CH	371 / Go Chee Han				
Description of Goods / Services								

Z REQUEST

Customer Request

M-BPNSUN

POLICY NO/ACC DATE : 1900149105-01 // 5-4-2021
DRIVE IN/TP VEH NUMBER : 5-4-2021 // GT1234Y - LONPAC
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY RH/FRONT FENDER & FRONT BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT, RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, CHECK HEADLAMP WITH FOCUS. NETT

M RH/FRONT FENDER

M RH/COVER BUMPER AREA

M FRONT BUMPER

M RIVET

1.00	914.43	00.00	914.43
1.00	229.67	00.00	229.67
1.00	1964.91	00.00	1964.91
10.00	4.81	00.00	48.10

1440 2400.00

1200 1500.00

380.00

120.00

Steve CLKK) WIL PL
12/4/21, 10.30am
4 Lyr
P/P
My Bel Sky

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis

Confirmed & accepted by

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on **Nett 7,557.11**
529.00

Total Payable 8,086.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany