

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004357/KPA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100489045
Claimant Vehicle No :	SGR7890Z	Insured Vehicle No :	SLH4413G
Date of Loss:	05/04/2021	Nature of Claim:	TP
		Claim No:	3263111152SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR7890Z		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ2689015
Reg. Date:	15/02/2007 (Man. Year: 2006)	Chassis No:	ZNE100324714
Colour:	Metallic Black	Odometer:	345024 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,305.05	2,825.20	1,479.85	34.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,570.00	310.00	16.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,185.05	4,395.20	1,789.85	28.94
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	6,185.05	3,500.00	2,685.05	43.41
+ GST 7.00/7.00% (S\$)	432.95	245.00	187.95	43.41
Nett Amount (S\$)	6,618.00	3,745.00	2,873.00	43.41
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,307.00		

INSPECTION

Date of Assignment:	06/04/2021	
Date Inspected:	07/04/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Mtg Cracked	598.10 FL	*581.00 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	58.40 FL	*58.40 FL
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*FRONT LH FENDER	Bent	705.80 FL	*705.80 FL
5	1		*FRONT LH FENDER LAMP	Missing	52.30 FL	*52.30 FL
6	1		*FRONT LH FENDER INNER SHIELD	Distorted	193.00 FL	*193.00 FL
7	1		*FRONT LH FENDER TRIANGLE GLASS	Serviceable	336.30 FL	*- FL
8	1		*FRONT LH DOOR	Bent	1,298.30 FL	*1,298.30 FL
9	1		*FRONT LH DOOR TOP HINGE	Repair	70.10 FL	*- FL
10	1		*FRONT LH DOOR SIDE MIRROR	Broken	523.80 FL	*523.80 FL
11	1		*FRONT LH SHOCK ABSORBER	Serviceable	506.40 FL	*- FL
12	1		*FRONT LH WHEEL BEARING	Serviceable	101.80 FL	*- FL
13	1		*FRONT LH KNUCKLE ARM	Serviceable	768.10 FL	*- FL
14	1		*FRONT LH SPORT RIM	Dented	380.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,613.40	3,683.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,308.35	858.40
Total Parts (S\$)	4,305.05	2,825.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT LH UNDER CARRIAGE	New	180.00	0.00
2	REMOVE & REFIX FRT LH FENDER ,FRT BUMPER ,FRT LH DOOR & ATTACHMENT TO KNOCK & REPAIR FRT LH W/SCREEN PILLAR & REALIGN THE SAME	New	680.00	600.00
3	REMOVE & REFIX FRT LH DOOR GLASS	New	60.00	60.00
4	PUTTY & RESPRAY ON FRT BUMPER ,FRT LH W/SCREEN PILLAR ,FRT LH DOOR ,FRT LH FEDER	New	850.00	800.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
6	RUSTPROOFING	New	50.00	50.00
Gross Labour Cost (\$\$)			1,880.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >