



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 8261T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLEBAR	BENT	180.00	180.00
2	HANDLEBAR GRIP LH & RH @\$23.00	NOT NECESSARY	46.00	-
2	HANDLEBAR BALANCER LH & RH @\$25.00	N/S CUT	50.00	25.00
1	HANDLEBAR LH CLUTCH LEVER	BENT	40.00	40.00
2	HANDLEBAR SIDE MIRROR LH & RH @\$25.00	N/S CUT	50.00	25.00
1	HEADLAMP	NOT NECESSARY	400.00	-
1	HEADLAMP TOP FAIRING (NUMBER PLATE)	NOT NECESSARY	160.00	-
1	HEADLAMP SIDE/HOLDER GARNISH	NOT NECESSARY	140.00	-
2	FRONT FORKS @\$600.00	BENT	1,200.00	1,200.00
1	FRONT FORK STEM	DAMAGED	200.00	200.00
1	SET FRONT FORK STEM BEARINGS	NECESSARY	150.00	150.00
1	FRONT FORK UPPER BRACKET	BENT	140.00	140.00
1	FRONT FORK LOWER BRACKET	NOT NECESSARY	140.00	-
1	FRONT FENDER/MUDGUARD	CUT	160.00	160.00
1	FRONT RIM	NOT NECESSARY	400.00	-
1	SET FRONT RIM BEARINGS	NOT NECESSARY	110.00	-
1	FRONT RIM SLIDER (LONG BOLT)	NOT NECESSARY	45.00	-
1	FRONT RIM SLIDER NUT	NOT NECESSARY	10.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	160.00	-
1	FRONT BRAKE CALIPER ASSEMBLY	NOT NECESSARY	220.00	-
1	RIDER-GEAR LEVER LH	BENT	40.00	40.00
	LESS 10% DISCOUNT		-404.10	-216.00
			3,636.90	1,944.00
	<u>SPECIAL NETT ITEMS</u>			
1	HANDLEBAR HANDPHONE HOLDER (SN)	NOT NECESSARY	70.00	-
1	HANDLEBAR ERP IU UNIT (SN)	NOT NECESSARY	180.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	120.00	-
1	FRONT NUMBER PLATE (SN)	BENT	15.00	15.00
1	HANDLEBAR LH CLUTCH-PROTECTOR (SN)	NOT NECESSARY	50.00	-
			435.00	15.00

Report Ref No. CS/INC21004358/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	LABOUR CHARGE.		400.00	250.00
	SPRAY PAINT AND MISC STICKERS.		200.00	150.00
	RELEASE & RENEW-BRAKE FLUID BLEEDING.		100.00	30.00
	CHASSIS ALIGNMENT-FRONT FORK STEM.		250.00	100.00
			950.00	530.00
GRAND TOTAL			5,021.90	2,489.00

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,489.00
--	--	--	-----------------

Report Ref No. CS/INC21004358/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.