

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SLQ9175M

Model: Honda Civic

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front right door / <i>pp</i>	\$ 1,200.00 <i>808</i>
1	Rear right door <i>X R</i>	\$ 1,200.00
1	Rear right fender <i>X R</i>	\$ 1,000.00
1	Right sideskirt <i>X R</i>	\$ 1,000.00
1	Power window motor / <i>BT</i>	\$ 500.00 <i>292.</i>
		<u>1,100</u>
		<u>- 20%</u>
		880

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 4,900.00

c/f: \$

\$ 4,900.00

Special Nett Items

AMT S\$

\$ -

S/N. Labour Charges

1	Remove and refit rear Panel	\$ 400.00	/
2	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00	30
3	Remove and refit inner garnishes trim to assist repair X NN	\$ 200.00	X
4	To apply undercoating on replaced panel	\$ 120.00	40
5	To Respray Painting.	\$ 1,000.00	700
		<u>1,170</u>	

\$ 1,870.00

GRAND TOTAL

\$ 6,770.00

880
1,170
2,050
-20%
1,640

L/S
\$1,650
3 days