

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004382/BTF3E2

Date: 04/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00034152100
Claimant Vehicle No: SLT4774B Insured Vehicle No: SLT5826D
Date of Loss: 02/04/2021 Nature of Claim: TP Claim No: SNM21D201871/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT4774B
Make & Model: MAZDA MAZDA5, 2.0 WAGON AT EU6 (A) Engine No: PE10520690
Reg. Date: 30/10/2017 (Man. Year: 2017) Chassis No: JM6CW1071H0126168
Colour: Blue Odometer: 97029 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,586.80	2,170.08	5,416.72	71.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	430.00	1,870.00	81.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,886.80	2,600.08	7,286.72	73.70
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	9,886.80	2,050.00	7,836.80	79.27
+ GST 7.00/7.00% (S\$)	692.08	143.50	548.58	79.27
Nett Amount (S\$)	10,578.88	2,193.50	8,385.38	79.27

INSPECTION

Date of Assignment: 06/04/2021
Date Inspected: 07/04/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2021)
Parts:	M1-SUV	MAZDA MAZDA5 2.0 WAGON AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT4774B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,309.00 FL	*1,082.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER BEAM	Not Damaged	532.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	66.00 FL	*37.80 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	66.00 FL	*37.80 FL
6	1		*FRONT BUMPER FOG LAMP LH	Not Damaged	340.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Not Damaged	79.00 FL	*- FL
8	1		*HEADLAMP RH	Broken	1,682.00 FL	*1,482.00 FL
9	1		*HEADLAMP BRACKET RH	Broken	43.00 FL	*43.00 FL
10	1		*HEADLAMP CLIPS	No such part	15.00 FL	*- FL
11	1		*FRONT FENDER RH	Not Damaged	323.00 FL	*- FL
12	1		*FRONT FENDER INNER COWLING LH	Not Damaged	211.00 FL	*- FL
13	1		*FRONT FENDER INNER COWLING CLIPS	Not Damaged	30.00 FL	*- FL
14	1		*FRONT SHOCK ABSORBER RH	Not Damaged	457.00 FL	*- FL
15	1		*FRONT UPPER ARM RH	Not Damaged	421.00 FL	*- FL
16	1		*FRONT CONTOR ARM RH	Not Damaged	425.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	Not Damaged	874.00 FL	*- FL
18	1		*FRONT WHEEL BEARING RH	Not Damaged	489.00 FL	*- FL
19	1		*FRONT LOWER ARM RH	Not Damaged	654.00 FL	*- FL
20	1		*FRONT TYRE RH	Not Damaged	350.00 FS	*- FS
21	1		*FRONT SPORTS RIM RH	Not Damaged	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,196.00	2,712.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,609.20	542.52
Total Parts (\$\$)	7,586.80	2,170.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	800.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	700.00	200.00
3	TUFF COAT	New	100.00	0.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX UNDERCARRIAGE	New	350.00	0.00
6	CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			2,300.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >