



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SME9913B Honda PI Model

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy / DO	\$ 880.00
2	2	Front bumper side retainer / BR	\$ 180.00
3	2	Front bumper bracket Xsu	\$ 190.00 X
5	1	Front panel lower support metal piece / OT	\$ 295.00
6	1	Front center chrome (Grille bar only) / BR	\$ 785.00 450
7	1	Front bumper lower grille / BR	\$ 350.00
22	1	Front light left / BR	\$ 880.00
23	1	Front light right / BR	\$ 880.00
24	1	Front light support frame (RH) / BR	\$ 195.00
25	1	Front light support bracket (LH) / BR	\$ 195.00
26	1	Front bonnet X R	\$ 1,800.00 X
27	1	Bonnet inner garnish seal Xnn	\$ 220.00 X
28	1	Bonnet lock assy with sensor Xnn	\$ 325.00 X
29	1	Horn Xnn	\$ 105.00 X
30	1	Radiator Xnn	\$ 950.00 X
31	1	Radiator frame Xnn	\$ 880.00 X
32	1	Reinforcement Xnn	\$ 380.00 X
		Sub-total	\$ 9,490.00

4308

20%

3444



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SME9913B Honda PI Model

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips / m	\$ 60.00 39
2	6	Front bumper lower grille clips / m	\$ 50.00 22
3	8	Front bonnet inner board clips X m	\$ 60.00 X
4	6	Front fender inner cowling clips X m	\$ 30.00 X
5	8	Front support panel top garnish clips X m	\$ 30.00 X
6	1	Coolant and Gas X m	\$ 60.00 X
7	2	Front bumper 2 parking sensor X m	\$ 980.00 X
8	1	Front number plate with casing X m	\$ 80.00 X
9			
Special Nett Items Total			\$ 1,350.00
Total parts			\$ 10,305.00

50



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SME9913B Honda PI Model

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,500.00 250
2	Labour putty and spray painting front portion.	\$ 1,500.00 400
3	Labour to apply anti rust proofing to front left affected area	\$ 150.00 30
4	Labour to check wiring and focus front headlamp.	\$ 80.00 30
5	Labour to remove and install front bonnet lock mechanism	\$ 100.00 Xnn
6	Labour to remove and install and adjust the door alignment	\$ 120.00 Xnn
7	Labour to check and install aircon related system to facilitate the repair and refill gas and check leakage	\$ 120.00 Xnn
8	Labour to check, remove and replace aircon related radiator, high pressure and low pressure hose, check air-con, top up gas etc	\$ 150.00 Xnn
9	Labour to remove and install front parking sensor and inner cooler assy	\$ 150.00 Xnn
10	To balance front wheel.	\$ 100.00 Xnn
11	To conduct wheel alignment.	\$ 120.00 Xnn
12	To conduct chassis alignment	\$ 150.00 Xnn

Total labour : \$ 4,240.00

Total parts : 10,840.00

Total labour : 4,240.00

Total repair cost : 15,080.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

mm A-dL

3 days + 1 = 4 days

My AL sy

L/S

12/04/21 @ 1020

3444

50

710

4204

202

3363.20

45-3350

3 days