



## Section A - Accident Details

Registration Number	SHB792S
Case Reference Number	TAX/04/21/2008
Registration Date	11/2/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN POH HENG
Type of Accident	Side Swipe
Accident Date and Time	4/4/2021 6:35 PM
Accident Reported Date and Time	5/4/2021 11:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110354
Special Instruction to ARC, if any	BP / RIGHT PORTION
Prepared Date and Time	5/4/2021 10:31 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,494.00	\$540.00
Total Spare Part Cost	\$3,467.70	\$1,342.02
Total Other Cost	\$1,442.20	\$713.76
<b>TOTAL COST</b>	<b>\$7,079.90</b>	<b>\$2,895.78</b>
<b>Lump Sum Total</b>	<b>\$7,100.00</b>	<b>\$2,900.00 (L/S)</b>
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / Sompo
ARC / Surveyor Sign Off Date	09/04/2021 5:57 PM	09/04/2021 10:25 AM
Signature		
Remarks	Changed insurance FR MSIG TO SOMPO Total number of repair days = 4 days SUP = + 1 day	L/S, AFTER PAINT PHOTO

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0322	Invoice Number	
Quotation Date	21.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$300.00 ✓
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$300.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY SILL MEMBER PANEL RH	\$180.00	\$80.00 ✓
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$60.00 ✓
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,494.00</b>	<b>\$540.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$742.20	\$593.76 ✓
<b>Total Other Costs</b>	<b>\$1,442.20</b>	<b>\$713.76</b>

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair ✓
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	25.00	\$505.20	Replace	Replace ✓
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace ✓

NEC

R

NEC

NEC

} SVC

}

Def

CRU

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 20/04/2021  
User ID PohSuan

		42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair R	R
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given X	SVC
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X	SVC
Total					\$5,198.04		\$1,310.48			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		42450-47040	WHEEL HUB REAR	1.00	\$489.40	25.00	\$367.05	Replace	Replace Jam
Total					489.40		367.05		

1677.53 /  
 - 207  
 -----  
 1342.02 /  
 + 300.00 /  
 + 1253.76 /  
 -----  
 2895.78 /  
 -----  
 US \$2900 /  
 4 days

SHB 7925