



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004387/QKtf3e2	
			Date: 07/05/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3955P	Veh. Inspected	SHB 792S
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101067/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	06/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTDKN36U605758109	Colour	MAROON
	Odometer	651028 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	ATREZZO	6 mm
	L/H Front Tyre	195/65 R15	ATREZZO	6 mm
	R/H Rear Tyre	195/65 R15	ATREZZO	6 mm
	L/H Rear Tyre	195/65 R15	ATREZZO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/04/2021	Inspection Date	07/04/2021
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	