ASS. REC. BY: Sun Pin. REF: CS &SM621004	1387/Qk+f3
The state of the s	GNMENT
From: Date:	Veh No: SHB7925. Yr Regn: 11/02/2015
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry Taxiv Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Prius c.c 1795
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 65/028- T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTDKN36460578109
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rîm / STD A/Rim or
	Tyre Size: F: 195/65 R15
(Policy Condition)	R: [95/65 R15
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or ATrezzo
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm / R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 6 104/201 D.O.I. 07/04/2021
Lum Sum: % 3 Val.: Yes or No	Survey held at SVIKT.
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	To
	TAX/04/21/2008
	XE 3955 P
	X = 2 1,37 f
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	: Site Insp (\$ _ )s+Rssi
	: Interview (\$ ) Photos
Report Formal :	: Tech. Invs (\$ ) Others
Lump Sum / LBJ: (% )	:Weekend (\$
	TOTAL

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	
Owner ID:	Company
Vehicle Details	369K
/ehicle No.:	SHB792S
/ehicle to be Exported:	No
ntended Deregistration Date:	09 Apr 2021
/ehicle Make:	TOYOTA
/ehicle Model:	PRIUS TAXI (SMRT)
rimary Colour:	Maroon
Nanufacturing Year:	2014
ngine No.:	2ZR6300529
hassis No.:	JTDKN36U605758109
Maximum Power Output:	100.0 kW (134 bhp)
pen Market Value:	\$32,920.00
Original Registration Date:	11 Feb 2015
irst Registration Date:	11 Feb 2015
ransfer Count:	0
ctual ARF Paid: ntended PARF Rebate Details	\$8,088.00
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	10 Feb 2023
ARF Rebate Amount: ntended COE Rebate Details	\$5,257.00
OE Expiry Date:	10 Feb 2023
OE Category:	A - Car up to 1600cc & 97kW (130bhp)
OE Period(Years):	8
QP Paid:	\$52,904.00
OE Rebate Amount:	\$12,143.00
otal Rebate Amount: lessage	\$17,400.00

The information contained herein is correct as at 09 Apr 2021



SS1E21460001 / SMRT AUTOMOTIVE SERVICES PTE LTD ENTRY DATE & TIME: 06/04/2021 09:34 (SGT) SUBMITTED BY: SHANTI B THAIYAL NAYAGI (SMRT05) VERSION: 1 (06/04/2021 09:34 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

06/04/2021 09:34 (SGT) 04/04/2021 18:35 (SGT) Bedok North Rd, Singapore BEDOK NORTH ROAD TOWARDS PIE Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**SHB792S** 

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes SMRT TAXIS PTE LTD 1XXXXX369K

TARC@SMRT.COM.SG (Phone) +65-68662671 (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Toyota Prius

No - Claiming third party

Taxi Auto 1800

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

DRIVER

Name of Driver NRIC No

MS First Capital Insurance Ltd ThirdParty Yes D-21097466MFSH

TAN POH HENG SXXXX125A



Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

XE3955P

Commercial vehicle

## WITNESS DETAILS

WITNESS 1

Name

MISS TAN

Phone

Email

Pescribe Circumstances of		
	tte en	
The second secon		
		_
eclaration		
Ve declare the foregoing particula	rs are true in every respect.	
	S (4   702   124)  Driver's Signature (# driver is not the policyholder)   Date	Mu 5/4/202
	2 1 1 1 1 1 1 1 1 1 1	



## Case Details

Case Reference Number :

TAX/04/21/2008

Type of Repair : Accident Repair

Vehicle Registration Number: SHB792S

Company Type: SMRT Taxis Pte Ltd

Estimation ID : EST-14461-ID
Assigned By : Taxi Claims Manager

Team

Insurance Company Name: Sompo Insurance Singapore Pte.

Ltd

Accident Date and Time: 04/04/2021 10:35 AM

Vehicle Age(In Months): 74

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## **Estimation Details**

### Spare Part's Cost Detail

				SMRT Reco	mmer	ndation						Surv	reyor Approval
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace V NCC
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0.00	Repair v X
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace V/Nec
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace Y/NR
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0.00	Not Giv€ ✓ X
One Time Key In	Main			WHEEL HUB REAR	1	489.40	489.40	25.00	367.05	Replace	0	0.00	Not Giv∈ ✓ 📈
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	0	0.00	Not Giv∈ ✓ X
Standard	Main		6505606	MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	471.52	Replace > / Def.
Standard	Main		6505486	DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	668.15	Replace Y / CNY
Standard	Main		6505658	WHEEL	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0.00	Repair YX R.
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	0	0.00	Not Giv€ ▼
Standard	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Not Giv∈ ✓ 💢
						To	tal Spare Pa	art Cost	3 967 57		S	Irvevor Total	1 229 07

Total Spare Part Cost 3,967.57

Surveyor Total 1,229.07

Lump Sum Discount (%) 20.00

Lump Sum Dis (%)

Final Spare Part Cost 3,174.06

Final Sur Total 983.26

### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Remarks Adjustment(\$)
1	Main	TO REPAIR RH PORTION	676.00	300.00
Total:			676.00	300.00

## Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Remarks Adjustment(\$)
1	Main	TO RESPRAY SILL MEMBER PANEL RH	180.00	80.00
2	Main	TO RESPRAY REAR DOOR RH	378.00	200.00
3	Main	TO RESPRAY REAR FENDER RH	378.00	200.00
4	Main	TO RESPRAY RIM	180.00	60
5	Main	TO RESPRAY REAR BUMPER	378.00	0.00
Total:			1,494.00	540.00

### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00	
3	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
6	Main	TO WASH AND VACUUM	60.00	0.00	
7	Main	TO TRANSFER DOOR MECHANISM	120.00	60	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	742.20	593.76	REAR DOOR, MOULDING BODY& REAR FENDER (RH)
Total:			1,442.20	713.76	

# Summary

Estimator Assesment(\$)

Surveyor Assesment(\$)

Survey Date

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,174.06	983.26
Total Labour Cost	676.00	300.00
Total Spray Painting	1,494.00	540.00
Other	1,442.20	713.76
Overall Total	6,786.26	2,537.02
Lump Sum Repair Option		
Lump Sum Total	6,800.00	2,550.00
Surveyor Approved Amount		2,550.00
No of Repair Days*	5	3
Remarks	Changed insurance FR MSIG TO SOMPO	L/S, AFTER PAINT PHOTO
		Sun Pin (LKK)
Surveyor Name		Sun Pili (ERR)
Signature	d	Joe

07/04/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: