



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Olivia Hwai Fang Loh Mrs Olivia
	Reg No/Reg Date	SLW3478Y / 08/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFJ411MJ5761800
	Engine No	G4FGHH691742
	Make/Model	KIA/FORTE K3 1.6 A L 189
Colour/Trim		B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/04/2021/ 15:11	QUK	282 / Kevin Leong	31542.			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	2	REPLACE REAR LH FENDER, REAR <sup>1</sup> BUMPER & AFFECTED AREA 3 X 400			1200			2400.00
REPAIR ON REAR LH DOOR								1050.00
E PNT98000		PAINT WORK ON REAR <sup>1</sup> LH DOOR, REAR LH <sup>1</sup> FENDER & REAR <sup>1</sup> BUMPER 3 X 350			60			120.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST						120.00
E PNT88000		REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR (photo)						120.00
E PNT88000		REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR (photo)						400.00
A 13900099		REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR (photo)						240.00
E PNT88000		REMOVE & INSTALL REAR WINDSCREEN GLASS						80.00
M SUNDRY		TO APPLY WINDSCREEN SEALANT			40			80.00
M SUNDRY		PERFORM RUST PREVENTION			40			80.00
M SUNDRY		TO APPLY BODY SEALANT ON AFFECTED AREA						400.00
A 34900099		REPLACE REAR UNDERCARRIAGE						120.00
A WHEELALIGNMENTBP		To Conduct Computerize Full Wheel Alignment						30.00
M SUNDRY		TO TRANSFER REAR LH RIM INCLUDING BALANCING						30.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						120.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						380.00
M SUNDRY								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Olivia Hwai Fang Loh Mrs Olivia Reg No/Reg Date SLW3478Y / 08/02/201 Date In/Mileage / 0 Chassis No KNAFJ411MJ5761800 Engine No G4FGHH691742 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/04/2021/ 15:11	QUK	282 / Kevin Leong	31542			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO SUPPLY SPORT RIM								20 50.00
M	SUNDRY							
	SUNDRIES				1.00	1213.00	20.00	970.40
M	PANEL ASSY-QUARTER OUTER, LH				1.00	688.00	20.00	550.40
M	COVER-RR BUMPER				1.00	29.00	20.00	23.20
M	BRACKET-RR BUMPER SIDE MTG, LH				1.00	27.00	20.00	21.60
M	FILM-ANTI CHIPPG LH				1.00	75.00	20.00	60.00
M	GUARD ASSY-REAR WHEEL, LH				1.00	534.00	20.00	427.20
M	GLASS ASSY-REAR WINDOW				2.00	4.00	20.00	6.40
M	STOPPER-RR WINDOW GLASS				10.00	2.00	20.00	16.00
P	PAD-WINDSHIELD GLASS							

Estimate

Stere (LKK)  
7/4/21, 4.30pm

00-AM AL  
EXCISE-?  
P/P  
My Belong  
9 dys

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Confirm &amp; accepted by

7% GST on      Nett      7,895.20      552.66  
Total Payable      8,447.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.