

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

5-Apr-21

Our ref : TP/4968/21

Kong Kum Yew

7PA16.
Gulian

RE : estimate cost for vehicle no : SJM 8430C

1 pc	rear bumper	schd	\$	980.00	✓
1 pc	rear bumper retainer long	schd		135.00	✓
1 pc	rear bumper retainer short	schd		80.00	✓
1 pc	rear bumper rh reflector	schd		120.00	✓
5 pcs	rear bumper clips	schd		25.00	✓
1 pc	rear rh fender	schd	1316	1,760.00	+
1 pc	rear rh fender inner shield	torn	1184.40	176.00	✓
1 pc	rh taillamp	schd		569.40	+
				3,845.40	
less 10%				384.54	
				3,460.86	
1 pc	rear rh tyre	schd		400.00	snett +
1 pc	rear rh rim	schd	400	400.00	✓
Panel beating.				600.00	300.
Spray painting.				600.00	400
Wiring.				30.00	✓
Alignment.				80.00	✓
				5,570.86	
Plus 7% GST				389.96	
				5,960.82	

SD : Five thousand nine hundred sixty & cents eighty-two only.

Adrian Lj
L/S 05/04/21
03 days.

total: 2354.40
L/S: 1.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: