

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0287/2021/HR
DATE : 6-Apr-21
WIP : 22040

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

We took 18 days

18 Jun 21 - John

OWNER'S NAME : MS. SIM MAY LING AMY
ADDRESS : 27 WEST COAST PARK
#07-03
SINGAPORE 127720
TELEPHONE : HP +65 97450317
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070119748
VEHICLE NO : **SLB 1656 Z**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 17/8/2020
ENGINE NO : CZD 895498
CHASSIS NO : WAUZZZF30L1107533
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Apr-21
PLACE OF ACCIDENT : NEAR JURONG TOWN HALL

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1656 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00 \$	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00 \$	1,700.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$	400.00 \$	360.00
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$	800.00 \$	500.00
5	TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
6	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00 \$	480.00
SUB LABOUR CHARGES		: \$	4,140.00 \$	3,520.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1656 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN. <i>c/f</i>	S/N \$	400.00	\$ 3,520.00 \$ 400.00
8	TO REMOVE AN RENEW FRONT WINDSCREEN FOIL SENSOR AND RESET SYSTEM.	S/N \$	300.00	FOC
9	TO RENEW EXHAUST TURBO CHARGER AND OTHER ENGINE COMPONENTS.	S/N \$	480.00	\$ 480.00
10	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(3 days for lock carrier - all Q models)</i>	\$	6,300.00	\$ 3,000.00
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, RHS FRONT DOOR.	\$	5,300.00	\$ 2,360.00
12	Added labour - see attached	\$	2,980.00	\$ 2,330.00
13	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$	20,284.00	\$ 12,474.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	2	\$ 2,161.00	\$	1,728.40
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 118.00	\$	46.64
3	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	\$	173.20
4	FRONT BUMPER LOWER GRILLE CENTRE COVER	1	\$ 51.00		
5	FRONT BUMPER LOWER GRILLE - LH / RH	2	\$ 220.00	\$	88.00
6	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 190.00		
7	FRONT BUMPER SPOILER	1	\$ 383.00	\$	306.40
8	FRONT BUMPER BRACKET	1	\$ 21.00		
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 306.00	\$	244.00
10	FRONT RADIATOR GRILLE	1	\$ 1,433.00	\$	1,146.40
11	FRONT RADIATOR STRIKER PLATE	1	\$ 244.00	\$	194.80
12	FRONT RADIATOR COVER CAP	1	\$ 45.00	\$	35.60
13	FRONT RADIATOR BRACKET	1	\$ 41.00	\$	32.48
14	FRONT CAMERA	1	\$ 1,141.00		
15	FRONT BUMPER WIRING SET	1	\$ 676.00	\$	540.80
16	FRONT BUMPER CARRIER	1	\$ 916.00	\$	732.40
17	FRONT BUMPER GUIDE SECTION - LH / RH	1	\$ 78.00		
18	FRONT BUMPER TOP COVER	1	\$ 123.00	\$	98.00
19	FRONT BUMPER FOAM FILLER PIECE	1	\$ 102.00	\$	81.60
20	AIR CONDITIONER STICKER LABEL	1	\$ 8.00	\$	5.68
SUB TOTAL SPARE PARTS		:	\$ 8,474.00	\$	5,454.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	5,454.40
21	FRONT PARKING AID SENSOR	4	\$	976.00	\$ 390.24
22	FRONT PARKING AID SENSOR SEAL RING	4	\$	14.00	\$ 11.20
23	SIGNAL HIGH TONE HORN - LH	1	\$	137.00	
24	SIGNAL LOW TONE HORN - RH	1	\$	130.00	
25	SIGNAL HORN SPRING SHACKLE - LH / RH	2	\$	44.00	\$ 17.04
26	FRONT FENDER - LH / RH	2	\$	2,572.00	\$ 1,028.80
27	FRONT FENDER ATTACHMENT PARTS	1	\$	63.00	
28	FRONT FENDER BRACE - LH / RH	2	\$	176.00	
29	FRONT FENDER BRACKET - LH / RH	2	\$	64.00	\$ 24.88
30	FRONT BONNET	1	\$	3,508.00	\$ 2,806.40
31	FRONT BONNET HINGE - LH / RH	2	\$	146.00	\$ 115.52
32	FRONT BONNET ATTACHMENT PARTS	1	\$	296.00	
33	FRONT BONNET STRIKER - LH / RH	2	\$	220.00	\$ 175.20
34	FRONT BONNET SOUND ABS	1	\$	219.00	
35	FRONT BONNET IMPACT PROTECTION	1	\$	28.00	\$ 21.84
36	FRONT BONNET HINGE COVER - LH / RH	2	\$	82.00	
37	FRONT PLENUM CHAMBER COVER	1	\$	129.00	\$ 103.20
38	FRONT BONNET BOWDEN CABLE	1	\$	58.00	\$ 46.00
39	FRONT BONNET LOCK	2	\$	427.00	\$ 341.60
40	FRONT BONNET RELEASE ELEMENT	1	\$	58.00	\$ 46.00
SUB TOTAL SPARE PARTS		:	\$	8,046.00	\$ 10,582.32

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

				DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS	
		<i>c/f</i>			\$	10,582.32
41	FRONT BONNET RELEASE LEVER	1	\$	14.00	\$	11.20
42	FRONT BONNET RELEASE CABLE COVER	1	\$	10.00	\$	7.60
43	FRONT BONNET LOCK CABLE	1	\$	74.00		
44	FRONT BONNET STRUT	1	\$	104.00		
45	HEADLIGHT MOUNTING BEAM - LH / RH	2	\$	236.00	\$	188.80
46	HEADLIGHT - LH / RH	2	\$	11,178.00	\$	8,942.40
47	HEADLIGHT HEAT SINK	1	\$	781.00		
48	HEADLIGHT POWER MODULE	1	\$	758.00	\$	606.40
49	HEADLIGHT HOSE - RH	1	\$	24.00		
50	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	420.00		
51	HEADLIGHT LIFT CYLINDER HOSE	1	\$	80.00	\$	63.44
52	FRONT RADIATOR LOCK CARRIER	1	\$	1,272.00	\$	1,017.60
53	A/C CONDENSER	1	\$	551.00	\$	440.80
54	A/C REFRIGERANT LINE SEAL RING	1	\$	10.00	\$	7.28
55	EXPANSION VALVE O-RING	1	\$	7.00	\$	5.52
56	REFRIGERANT LINE LONG	1	\$	330.00	\$	264.00
57	REFRIGERANT LINE SHORT	1	\$	337.00	\$	269.60
58	REFRIGERANT LINE DUAL CLIP	1	\$	30.00		
59	TEMPERATURE SENSOR	1	\$	59.00		
60	TEMPERATURE SENSOR HOLDER	1	\$	7.00		
SUB TOTAL SPARE PARTS		:	\$	16,282.00	\$	22,406.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	22,406.96
61	ADDITIONAL RADIATOR COOLER	1	\$	920.00	\$ 736.00
62	RADIATOR COOLER	1	\$	1,035.00	\$ 828.00
63	RADIATOR COOLANT	4	\$	179.00	\$ 143.04
64	RADIATOR MOUNT BRACKET	2	\$	82.00	\$ 65.28
65	RADIATOR BUSH	2	\$	19.00	\$ 15.04
66	RADIATOR FAN	1	\$	1,529.00	\$ 1,223.20
67	RADIATOR AIR BAFFLE GUIDE - LH / RH	2	\$	76.00	\$ 59.52
68	RADIATOR AIR BAFFLE GUIDE - UPPER / LOWER	2	\$	84.00	\$ 33.04
69	RADIATOR INTAKE AIR DUCT	1	\$	29.00	\$ 22.72
70	INTAKE AIR INLET COVER	1	\$	56.00	\$ 44.48
71	INTAKE AIR GUIDE SHORT	1	\$	20.00	\$ 15.36
72	WATER DRAINAGE HOSE	1	\$	21.00	\$ 16.16
73	INTAKE AIR GUIDE LONG	1	\$	34.00	\$ 26.80
74	AIR FILTER	1	\$	239.00	\$ 191.20
75	INTAKE AIR DUCT	1	\$	47.00	\$ 37.52
76	INTAKE MANIFOLD	1	\$	121.00	
77	INTAKE CONNECTION	1	\$	610.00	\$ 488.00
78	AIR COOLER	1	\$	775.00	\$ 619.60
79	THROTTLE VALVE ADAPTER	1	\$	824.00	\$ 659.20
80	INTAKE RETAINING BAR	1	\$	15.00	
SUB TOTAL SPARE PARTS		:	\$	6,715.00	\$ 27,631.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	27,631.12
81	INTAKE PRESSURE SENSOR	1	\$ 194.00	\$	155.20
82	ALTERNATOR	1	\$ 2,499.00		
83	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$	428.80
84	FRONT WINDOW OUTER SLOT SEAL - RH	1	\$ 224.00	\$	179.20
85	FRONT WINDSCREEN	1	\$ 1,121.00	\$	896.80
86	RAIN SENSOR GEL FOIL	1	\$ 137.00	\$	109.20
87	RAIN SENSOR RETAINING SPRING	1	\$ 21.00		
88	FRONT NOISE INSULATION	1	\$ 397.00		
89	EXHAUST MANIFOLD	1	\$ 4,871.00		
90	EXHAUST MANIFOLD SEAL	1	\$ 15.00		
91	EXHAUST MANIFOLD THREADED PIN	4	\$ 23.00		
92	OIL FEED SEAL RING	2	\$ 11.00		
93	OIL TUBE SEAL RING	2	\$ 46.00		
94	INTAKE PIPE GASKET	2	\$ 27.00		
95	PREASURE PIPE SEAL	1	\$ 18.00		
96	FRONT NUMBER PLATE	S/N	\$ 60.00	\$	60.00
97	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	\$	200.00
98	SUPPLEMENTARY		\$ 1,625.00	\$	1,565.20
99	SUNDRIES		\$ 350.00	\$	227.60
TOTAL SPARE PARTS			\$ 51,892.00	\$	31,453.12
TOTAL LABOUR CHARGES			\$ 20,284.00	\$	12,474.00
GRAND TOTAL			\$ 72,176.00	\$	43,927.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-18/05/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0287/2021/HR 12-Apr-21 CHANG 1 of 1 SLB 1656 Z AUDI Q3 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT AND CLOSING ELEMENT.	\$ 2,000.00	\$ 1,500.00
2	TO RESPRAY RHS FRONT FENDER TOP SUPPORT.	\$ 700.00	\$ 550.00
3	TO RENEW AIRCON CONDENSER REFRIGERANT PIPES.	\$ 280.00	\$ 280.00
		\$ 2,980.00	\$ 2,330.00
<u>Parts</u>			
1	FRONT CAMARE SECURING PLATE	\$ 33.00	\$ 26.16
2	FRONT FENDER TOP SIDE MEMBER - RH	\$ 431.00	\$ 344.80
3	FRONT FENDER TOP CLOSING ELEMENT - RH	\$ 357.00	
4	COOLANT PIPE QUICK ACTING COUPLING - UPPER	\$ 18.00	\$ 13.76
5	REFRIGERANT LINE (A/C COMPRESSOR -> CUT-OFF POINT)	\$ 337.00	\$ 269.60
6	REFRIGERANT LINE BRACKET	\$ 27.00	\$ 20.88
7	PRESSURE PIPE	\$ 363.00	\$ 290.00
8	INTAKE HOSE CLAMPS	\$ 59.00	
9	ACRYLIC SEALER	\$ 180.00	\$ 180.00
10	CAVITY WAX	\$ 140.00	\$ 140.00
11	STONE CHIP	\$ 180.00	
12	METAL FILLER POWDER	\$ 280.00	\$ 280.00
	MATERIALS	\$ 2,405.00	\$ 1,565.20
	LABOUR	\$ 2,980.00	\$ 2,330.00
	GRAND TOTAL	\$ 5,385.00	\$ 3,895.20

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT