

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0287/2021/HR
DATE	:	6-Apr-21
WIP	:	22040

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MS. SIM MAY LING AMY
ADDRESS	:	27 WEST COAST PARK
	:	#07-03
	:	SINGAPORE 127720
TELEPHONE	:	HP +65 97450317
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070119748
VEHICLE NO	:	SLB 1656 Z
MODEL CODE	:	Q3 1.4 TFSI S TRONIC
MODEL YEAR	:	17/8/2020
ENGINE NO	:	CZD 895498
CHASSIS NO	:	WAUZZZF30L1107533
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	3-Apr-21
PLACE OF ACCIDENT	:	NEAR JURONG TOWN HALL




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1656 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,700.00	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 400.00	240360 /
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	500 /
5	TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X 11
6	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	
SUB LABOUR CHARGES		: \$ 4,140.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 1656 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN. <i>sales agent</i>	S/N \$ 400.00	/
8	TO REMOVE AN RENEW FRONT WINDSCREEN FOIL SENSOR AND RESET SYSTEM.	S/N \$ 300.00	? Xnn
9	TO RENEW EXHAUST TURBO CHARGER AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	? /
10	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>5.5 to 5.5 6 days @ 500</i>	6,300.00	2750 3000 /
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, RHS FRONT DOOR. <i>@ 550 4 + 20 + 80</i>	\$ 5,300.00	2360 /
12	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 17,304.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>turn ✓</i>	2 S	2,161.00	1728.40
2	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>cm ✓</i>	1 S	118.00	46.64
3	FRONT BUMPER GRILLE - CENTER <i>cm ✓</i>	1 S	217.00	173.20
4	FRONT BUMPER LOWER GRILLE CENTRE COVER <i>cm ✓</i>	1 S	51.00	
5	FRONT BUMPER LOWER GRILLE - LH / RH <i>cm ✓</i>	1 S	220.00	88
6	FRONT BUMPER CLOSING ELEMENT - CENTER <i>cm ✓</i>	1 S	190.00	
7	FRONT BUMPER SPOILER <i>cm ✓</i>	1 S	383.00	306.40
8	FRONT BUMPER BRACKET <i>cm ✓</i>	1 S	21.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cm ✓</i>	1 S	306.00	244
10	FRONT RADIATOR GRILLE <i>cm ✓</i>	1 S	1,433.00	1146.40
11	FRONT RADIATOR STRIKER PLATE <i>cm ✓</i>	1 S	244.00	194.80
12	FRONT RADIATOR COVER CAP <i>cm ✓</i>	1 S	45.00	35.60
13	FRONT RADIATOR BRACKET <i>cm ✓</i>	1 S	41.00	32.48
14	FRONT CAMERA <i>cm ✓</i>	1 S	1,141.00	
15	FRONT BUMPER WIRING SET <i>cm ✓</i>	1 S	676.00	540.80
16	FRONT BUMPER CARRIER <i>cm ✓</i>	1 S	916.00	732.40
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>cm ✓</i>	1 S	78.00	
18	FRONT BUMPER TOP COVER <i>cm ✓</i>	1 S	123.00	98
19	FRONT BUMPER FOAM FILLER PIECE <i>cm ✓</i>	1 S	102.00	81.60
20	AIR CONDITIONER STICKER LABEL <i>cm ✓</i>	1 S	8.00	5.68
SUB TOTAL SPARE PARTS		:	\$	8,474.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR ? nan ✓	2pc ✓	\$ 976.00	390.24
22	FRONT PARKING AID SENSOR SEAL RING nan ✓	4	\$ 14.00	11.20
23	SIGNAL HIGH TONE HORN - LH nan ✓	1	\$ 137.00	
24	SIGNAL LOW TONE HORN - RH nan ✓	1	\$ 130.00	
25	SIGNAL HORN SPRING SHACKLE - LH / RH nan ✓	1pc ✓	\$ 44.00	17.04
26	FRONT FENDER - LH / RH nan ✓	1pc ✓	\$ 2,572.00	1028.80
27	FRONT FENDER ATTACHMENT PARTS nan ✓	1	\$ 63.00	
28	FRONT FENDER BRACE - LH / RH nan ✓	2	\$ 176.00	
29	FRONT FENDER BRACKET - LH / RH nan ✓	1pc ✓	\$ 64.00	24.88
30	FRONT BONNET nan ✓	1	\$ 3,508.00	2806.40
31	FRONT BONNET HINGE - LH / RH nan ✓	2	\$ 146.00	115.52
32	FRONT BONNET ATTACHMENT PARTS nan ✓	1	\$ 296.00	
33	FRONT BONNET STRIKER - LH / RH nan ✓	2	\$ 220.00	175.20
34	FRONT BONNET SOUND ABS nan ✓	1	\$ 219.00	
35	FRONT BONNET IMPACT PROTECTION nan ✓	1	\$ 28.00	21.84
36	FRONT BONNET HINGE COVER - LH / RH nan ✓	2	\$ 82.00	
37	FRONT PLENUM CHAMBER COVER nan ✓	1	\$ 129.00	103.20
38	FRONT BONNET BOWDEN CABLE nan ✓	1	\$ 58.00	46
39	FRONT BONNET LOCK nan ✓	2	\$ 427.00	341.60
40	FRONT BONNET RELEASE ELEMENT nan ✓	1	\$ 58.00	46
SUB TOTAL SPARE PARTS		:	\$	8,046.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6941 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET RELEASE LEVER <i>see /</i>	1	\$ 14.00	11.20
42	FRONT BONNET RELEASE CABLE COVER <i>mis /</i>	1	\$ 10.00	7.60
43	FRONT BONNET LOCK CABLE <i>? xsu</i>	1	\$ 74.00	
44	FRONT BONNET STRUT <i>? xsu</i>	1	\$ 104.00	
45	HEADLIGHT MOUNTING BEAM - LH / RH <i>cm /</i>	2	\$ 236.00	188.80
46	HEADLIGHT - LH / RH <i>bro /</i>	2	\$ 11,178.00	8942.40
47	HEADLIGHT HEAT SINK <i>? xsu</i>	1	\$ 781.00	
48	HEADLIGHT POWER MODULE <i>? damaged /</i>	1	\$ 758.00	606.40
49	HEADLIGHT HOSE - RH <i>? xsu</i>	1	\$ 24.00	
50	HEADLIGHT LIFT CYLINDER - LH / RH <i>? xsu</i>	2	\$ 420.00	
51	HEADLIGHT LIFT CYLINDER HOSE <i>? cut /</i>	1	\$ 80.00	63.44
52	FRONT RADIATOR LOCK CARRIER <i>cm /</i>	1	\$ 1,272.00	1017.60
53	A/C CONDENSER <i>bt /</i>	1	\$ 551.00	440.80
54	A/C REFRIGERANT LINE SEAL RING <i>ne /</i>	1	\$ 10.00	7.28
55	EXPANSION VALVE O-RING <i>ne /</i>	1	\$ 7.00	5.52
56	REFRIGERANT LINE LONG <i>? bt /</i>	1	\$ 330.00	264.00
57	REFRIGERANT LINE SHORT <i>? bt /</i>	1	\$ 337.00	269.60 269.60
58	REFRIGERANT LINE DUAL CLIP <i>? xsu</i>	1	\$ 30.00	
59	TEMPERATURE SENSOR <i>? xsu</i>	1	\$ 59.00	
60	TEMPERATURE SENSOR HOLDER <i>? xsu</i>	1	\$ 7.00	
SUB TOTAL SPARE PARTS		:	\$	16,282.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	ADDITIONAL RADIATOR COOLER <i>bt/</i>	1	\$ 920.00	736
62	RADIATOR COOLER <i>bt/</i>	1	\$ 1,035.00	828
63	RADIATOR COOLANT <i>neu/</i>	4	\$ 179.00	143.04
64	RADIATOR MOUNT BRACKET <i>cm/</i>	2	\$ 82.00	65.28
65	RADIATOR BUSH <i>re/</i>	2	\$ 19.00	15.04
66	RADIATOR FAN <i>? cm/</i>	1	\$ 1,529.00	1223.20
67	RADIATOR AIR BAFFLE GUIDE - LH / RH <i>cm/</i>	2	\$ 76.00	59.52
68	RADIATOR AIR BAFFLE GUIDE - UPPER / LOWER <i>cm/</i>	1	\$ 84.00	33.04
69	RADIATOR INTAKE AIR DUCT <i>cm/</i>	1	\$ 29.00	22.72
70	INTAKE AIR INLET COVER <i>cm/</i>	1	\$ 56.00	44.48
71	INTAKE AIR GUIDE SHORT <i>cm/</i>	1	\$ 20.00	15.36
72	WATER DRAINAGE HOSE <i>mis/</i>	1	\$ 21.00	16.16
73	INTAKE AIR GUIDE LONG <i>cm/</i>	1	\$ 34.00	26.80
74	AIR FILTER <i>de/</i>	1	\$ 239.00	191.20
75	INTAKE AIR DUCT <i>? de/</i>	1	\$ 47.00	37.52
76	INTAKE MANIFOLD <i>? xon</i>	1	\$ 121.00	
77	INTAKE CONNECTION <i>? cm/</i>	1	\$ 610.00	488
78	AIR COOLER <i>bt/</i>	1	\$ 775.00	619.60
79	THROTTLE VALVE ADAPTER <i>? cm/</i>	1	\$ 824.00	659.20
80	INTAKE RETAINING BAR <i>? Xnn</i>	1	\$ 15.00	
SUB TOTAL SPARE PARTS		:	\$ 6,715.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 1656 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	INTAKE PRESSURE SENSOR <i>cm /</i>	1	\$ 194.00	<i>155.20</i>
82	ALTERNATOR <i>? xsu</i>	1	\$ 2,499.00	
83	FRONT WHEEL ARCH COVER - LH / RH <i>rec /</i>	2	\$ 536.00	<i>428.80</i>
84	FRONT WINDOW OUTER SLOT SEAL - RH <i>cut /</i>	1	\$ 224.00	<i>179.20</i>
85	FRONT WINDSCREEN <i>cm /</i>	1	\$ 1,121.00	<i>896.80</i>
86	RAIN SENSOR GEL FOIL <i>rec /</i>	1	\$ 137.00	<i>109.20</i>
87	RAIN SENSOR RETAINING SPRING <i>? xnn</i>	1	\$ 21.00	
88	FRONT NOISE INSULATION <i>? xsu</i>	1	\$ 397.00	
89	EXHAUST MANIFOLD <i>x su</i>	1	\$ 4,871.00	
90	EXHAUST MANIFOLD SEAL <i>x xnn</i>	1	\$ 15.00	
91	EXHAUST MANIFOLD THREADED PIN <i>x nn</i>	4	\$ 23.00	
92	OIL FEED SEAL RING <i>? xnn</i>	2	\$ 11.00	
93	OIL TUBE SEAL RING <i>? fan</i>	2	\$ 46.00	
94	INTAKE PIPE GASKET <i>? xnn</i>	2	\$ 27.00	
95	PRESURE PIPE SEAL <i>? fan</i>	1	\$ 18.00	
96	FRONT NUMBER PLATE <i>lt /</i>	S/N	\$ 60.00	<i>/</i>
97	FRONT WINDSCREEN SEALANT <i>nn /</i>	S/N	\$ 200.00	<i>/</i>
98	SUNDRIES <i>? rec /</i>	\$	350.00	<i>227.60</i>
TOTAL SPARE PARTS		:	\$ 50,267.00	
TOTAL LABOUR CHARGES		:	\$ 17,304.00	
GRAND TOTAL		:	\$ 67,571.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.