

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0284/2021/ET
DATE : 6-Apr-21
WIP : 22172

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : PECK JEN JEN
ADDRESS : 33 PHENG GECK AVE #15-11.
SINGAPORE 348228
TELEPHONE : HP +65 9636 6271
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800097991-02
VEHICLE NO : **SMD 2020 D**
MODEL CODE : TT COUPE 1.8 TFSI S TRONIC
MODEL YEAR : 23/8/2018
ENGINE NO : CJS 278388
CHASSIS NO : TRUZZZFV7J1015021
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Apr-21
PLACE OF ACCIDENT : X-JUNCTION @ GEYLANG RD / TANJONG KATONG RD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 9574 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK & TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS RMMOVED	\$	2,100.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$	<u><u>5,122.00</u></u>

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Smp 2020P

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT9574R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,506.00	<i>✓ 2004.80</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 486.00	<i>+</i>
3	FRONT BUMPER CLOSING ELEMENT - RH <i>Broken.</i>	1	\$ 111.00	<i>✓ 88.80</i>
4	FRONT BUMPER SECURING STRIP - RH <i>Not new</i>	1	\$ 43.00	<i>? X</i>
5	FRONT BUMPER LOWER GRILLE - CENTRE <i>new</i>	1	\$ 161.00	<i>+</i>
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 156.00	<i>+</i>
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	1	\$ 217.00	<i>✓ 173.20</i>
8	RADIATOR GRILLE <i>new</i>	1	\$ 1,359.00	<i>+</i>
9	INNER COVER <i>new</i>	1	\$ 65.00	<i>+</i>
10	RADIATOR GRILLE COVER <i>new</i>	1	\$ 107.00	<i>+</i>
11	FRONT BUMPER LOWER COVER - RH <i>new</i>	1	\$ 56.00	<i>+</i>
12	FRONT BUMPER REINFORCEMENT <i>? nn</i>	1	\$ 1,084.00	<i>? X</i>
13	FRONT BUMPER FOAM FILLER <i>cut</i>	1	\$ 129.00	<i>✓ 103.20</i>
14	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 127.00	<i>+</i>
15	FRONT BUMPER GUIDE SECTION - RH <i>Not new</i>	1	\$ 39.00	<i>? X</i>
16	FRONT BUMPER PARKING SENSOR <i>Not new</i>	1	TBC	<i>? X</i>
17	SENSOR 'O' RUBBER SEAL <i>Not new</i>	4	\$ 14.00	<i>? X</i>
18	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 577.00	<i>+</i>
19	SIGNAL HORN - RH LOW TONE <i>Not new</i>	1	\$ 286.00	<i>? X</i>
20	LED HEADLIGHT <i>cut</i>	1	\$ 7,926.00	<i>✓ 6340.80</i>
SUB TOTAL SPARE PARTS			\$ 15,449.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

SMP 2020P

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT9574R

		DAMAGED PA	
S/N	PARTS DESCRIPTION	QTY	S/NETT
21	HEADLIGHT LIFT CYLINDER - RH <i>scrubed</i>	1 \$	159.00 ✓ 127.20
22	HEADLIGHT LIFT CYLINDER BRACKET - RH <i>Damaged.</i>	1 \$	29.00 ? 23.20
23	WATER HOSE <i>xll m</i>	1 \$	77.00 +
24	FRONT FENDER - RH <i>xll m</i>	1 \$	1,188.00 +
25	FRONT FENDER ATTACHMENT PARTS - RH <i>xll m</i>	1 \$	40.00 +
26	FRONT FENDER <i>Brace</i> BRACKET - RH <i>Bent.</i>	1 \$	118.00 ✓ 94.40
27	FRONT FENDER BRACKET - RH UPPER <i>7 xll m</i>	1 \$	50.00 +
28	FRONT FENDER BRACKET - CENTRE RH UPPER	1 \$	44.00 +
29	FRONT FENDER INNER GARNISH - RH	1 \$	170.00 +
30	FRONT FENDER INNER GARNISH ATTACHMENT PARTS - RH <i>M</i>	1 \$	112.00 +
31	FRONT WHEEL HOUSING LINER - RH <i>2</i>	1 \$	117.00 +
32	AIR GUIDE - RH	1 \$	35.00 +
33	AIR GUIDE SEAL - RH <i>1 xll m</i>	1 \$	8.00 +
34	SEAL STRIP INSERT - FILLER PIECE	1 \$	4.00 +
35	FRONT NO. PLATE	S/N \$	60.00 +
36	SUNDRIES <i>7th Dec.</i>	1 \$	200.00 . X
TOTAL SPARE PARTS		:	\$ 17,860.00
TOTAL LABOUR CHARGES		:	\$ 5,122.00
GRAND TOTAL		:	\$ 22,982.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
 SURVEYED DATE : *06/04/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 03 Days*
slg.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT