

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0284/2021/ET
DATE : 6-Apr-21
WIP : 22172

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

18-Jun-21

OWNER'S NAME : PECK JEN JEN
ADDRESS : 33 PHENG GECK AVE #15-11.
SINGAPORE 348228
TELEPHONE : HP +65 9636 6271
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800097991-02
VEHICLE NO : **SMD 2020 D**
MODEL CODE : TT COUPE 1.8 TFSI S TRONIC
MODEL YEAR : 23/8/2018
ENGINE NO : CJS 278388
CHASSIS NO : TRUZZZFV7J1015021
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Apr-21
PLACE OF ACCIDENT : X-JUNCTION @ GEYLANG RD / TANJONG KATONG RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 2020 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK & TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 1,972.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 2020 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,506.00	\$	2,004.80
2	FRONT BUMPER FIXING PARTS	1	\$ 486.00		
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 111.00	\$	88.80
4	FRONT BUMPER SECURING STRIP - RH	1	\$ 43.00		
5	FRONT BUMPER LOWER GRILLE - CENTRE	1	\$ 161.00		
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 156.00		
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 217.00	\$	173.20
8	RADIATOR GRILLE	1	\$ 1,359.00		
9	INNER COVER	1	\$ 65.00		
10	RADIATOR GRILLE COVER	1	\$ 107.00		
11	FRONT BUMPER LOWER COVER - RH	1	\$ 56.00		
12	FRONT BUMPER REINFORCEMENT	1	\$ 1,084.00		
13	FRONT BUMPER FOAM FILLER	1	\$ 129.00	\$	103.20
14	FRONT BUMPER TOP COVER	1	\$ 127.00		
15	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00		
16	FRONT BUMPER PARKING SENSOR	1	TBC		
17	SENSOR 'O' RUBBER SEAL	4	\$ 14.00		
18	FRONT BUMPER WIRING SET	1	\$ 577.00		
19	SIGNAL HORN - RH LOW TONE	1	\$ 286.00		
20	LED HEADLIGHT	1	\$ 7,926.00	\$	6,340.80
SUB TOTAL SPARE PARTS		:	\$ 15,449.00	\$	8,710.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 2020 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 8,710.80</i>
21	HEADLIGHT LIFT CYLINDER - RH	1	\$ 159.00	<i>\$ 127.20</i>
22	HEADLIGHT LIFT CYLINDER BRACKET - RH	1	\$ 29.00	<i>\$ 23.20</i>
23	WATER HOSE	1	\$ 77.00	
24	FRONT FENDER - RH	1	\$ 1,188.00	
25	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 40.00	
26	FRONT FENDER BRACKET - RH	1	\$ 118.00	<i>\$ 94.40</i>
27	FRONT FENDER BRACKET - RH UPPER	1	\$ 50.00	
28	FRONT FENDER BRACKET - CENTRE RH UPPER	1	\$ 44.00	
29	FRONT FENDER INNER GARNISH - RH	1	\$ 170.00	
30	FRONT FENDER INNER GARNISH ATTACHMENT PARTS - RH	1	\$ 112.00	
31	FRONT WHEEL HOUSING LINER - RH	1	\$ 117.00	
32	AIR GUIDE - RH	1	\$ 35.00	
33	AIR GUIDE SEAL - RH	1	\$ 8.00	
34	SEAL STRIP INSERT - FILLER PIECE	1	\$ 4.00	
35	FRONT NO. PLATE	S/N	\$ 60.00	
36	SUNDRIES	1	\$ 200.00	
TOTAL SPARE PARTS			: \$ 17,860.00	<i>\$ 8,955.60</i>
TOTAL LABOUR CHARGES			: \$ 5,122.00	<i>\$ 1,972.00</i>
GRAND TOTAL			: \$ 22,982.00	<i>\$ 10,927.60</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-01/06/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT