

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004400/QGS3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100476278
Claimant Vehicle No :	SMB5003U	Insured Vehicle No :	SLE4912Z
Date of Loss:	30/03/2021	Nature of Claim:	TP
		Claim No:	4560540692SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB5003U	Engine No:	22120870
Make & Model:	ALEXANDER DENNIS ENVIRO500, 8.8 D (A)	Chassis No:	SFD76CLR5EMTL3463
Reg. Date:	10/09/2014 (Man. Year: 2014)	Odometer:	516814 km
Colour:	Silver		
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	305/70 R22.5	Rear Tyre Size:	305/70 R22.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	109.50	98.55	10.95	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,938.00	1,238.00	700.00	36.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,047.50	1,336.55	710.95	34.72
Approved Total (Overridden) (\$\$)		1,300.00		
Nett Amount (\$\$)	2,047.50	1,300.00	747.50	36.51
+ Loss of Use (3.0 x S\$280.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		2,147.00		
Global Sum Settlement (\$\$)		2,100.00		

INSPECTION

Date of Assignment:	05/04/2021	
Date Inspected:	05/04/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER:4 WAY VALVE DOOR MAN A22,A24 A95	Crumpled	109.50 F	*109.50 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					109.50	109.50
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	10.95
Total Parts (S\$)					109.50	98.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR LHS PORTION	New	1,060.00	530.00
2	TO PUTTY & RESPRAY	New	878.00	708.00
Gross Labour Cost (S\$)			1,938.00	1,238.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >