



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMX9556Z

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 49316
Reg No/Reg Date SMX9556Z / 22/11/2018
Date In/Mileage 08/04/2021 / 45740
Chassis No WDD2130422A455744
Engine No 27492031479139
Make/Model MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE
Colour/Trim 028 890 Cavansite B/ 042 215 Leather Mac

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	04/07/2021/ 12:45	YK	395 / Yik Chan Hoe					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : DMPCSNW00188352000 // 31/03/2021									
DRIVE IN/EXCESS : TOW IN 01/04/2021 // NIL									
DATE IN/DATE SURVEY: 07/04/2021 // STEVE LKK									
BY/AUTHORIZED ON : 08/04/2021 @ 1445 // HUI ZHEN LKK									
S BPNSUB									
SUPPLY & INSTALL HUPER OPTIK WINDOW FILM ON : REAR WINDSCREEN									300.00
A BPILAB									
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH									960.00
A BPIRES									
RESPRAY RIGHT REAR FENDER AND BOOT LID.									1200.00
A BPILAB									
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT								0.10	380.00
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET									120.00
A BPILAB									1920.00
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS									
A BPILAB								0.07	560.00
RENEW REAR W/SCREEN									1200.00
S BPNSUB									
REMOVE AND REFIT REAR SEAT FRAME, REPLACE REAR SEAT LEATHER UPHOLSTERY COVERING									960.00
A BPILAB									
REPLACE HEADLINER									140.00
S BPNTOW									
ACCIDENT TOWING FR 607 HOUGANG AVE 4 TO PLSC USING KING DOLLEY									

Attn: **Steve**
10 Working Days

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMX9556Z

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
6222366

Vehicle & Document Information

WIP No **49316**
Reg No/Reg Date **SMX9556Z / 22/11/2018**
Date In/Mileage **08/04/2021/ 45740**
Chassis No **WDD2130422A455744**
Engine No **27492031479139**
Make/Model **MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE**
Colour/Trim **028 890 Cavansite B/ 042 215 Leather Mac**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	04/07/2021/ 12:45	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WO: 185188				
X REAR W/SCREEN	1.00	1508.32	00.00	1508.32
X ONE-COMPONENT ADHESIVE	2.00	160.11	00.00	320.22
X BOOT LID MERCEDES STAR	1.00	53.06	00.00	53.06
X GROMMET	3.00	2.64	00.00	7.92
X BOOT LID CHROME MOULDING	1.00	146.33	00.00	146.33
X BOOT LID E200 MODEL PLATE	1.00	93.61	00.00	93.61
X REAR HAT TRAY TRIM	1.00	1831.40	00.00	1831.40
X REAR W/SCREEN ROLLER BLIND	1.00	3109.74	00.00	3109.74
X REAR SEAT BACKREST LEATHER UPHOLSTRY	1.00	3334.44	00.00	3334.44
X HEADLINER	1.00	1754.19	00.00	1754.19
X RIGHT REAR TRIM BOARD BRACKET	1.00	14.17	00.00	14.17

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett **19,913.40**
7% GST on **19913.40** **1393.94**
Total Payable 21,307.34

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMX9556Z

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
6222366

Vehicle & Document Information

WIP No **49316**
Reg No/Reg Date **SMX9556Z / 22/11/2018**
Date In/Mileage **08/04/2021/ 45740**
Chassis No **WDD2130422A455744**
Engine No **27492031479139**
Make/Model **MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE**
Colour/Trim **028 890 Cavansite B/ 042 215 Leather Mac**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	04/07/2021/ 12:45	YK	395 / Yik Chan Hoe
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
X RIGHT REAR TRIM BOARD BRACKET	1.00	14.17	00.00	14.17

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 14.17** **0.99**

Total Payable 15.16

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

