



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMX9556Z

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 49316
Reg No/Reg Date SMX9556Z / 22/11/2018
Date In/Mileage 0
Chassis No WDD2130422A455744 45708
Engine No 27492031479139
Make/Model MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE
Colour/Trim 028 890 Cavansite B/ 042 215 Leather Mac

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	05/04/2021/ 11:17	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPCSNW00188352000 // 31/03/2021								
DRIVE IN/EXCESS : TOW IN 01/04/2021 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								
INSTALL SOLAR FILM ON REAR W/SCREEN								300.00 ✓
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH								960 2400.00
A BPIRES								
RESPRAY RIGHT REAR FENDER, LEFT REAR FENDER, REAR BUMPER AND BOOT, LID.								1200 3000.00
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT							0.10	380.00 ✓
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET								120.00 ✓
A BPILAB								
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS (photo Dismantle)								1920 2400.00
A BPILAB								
RENEW REAR W/SCREEN							0.07	560.00 ✓
S BPNSUB								
REPLACE REAR SEAT LEATHER UPHOLSTERY COVERING								1200.00 ✓
A BPILAB								
REPLACE HEADLINER								960 1200.00
S BPNTOW								
ACCIDENT TOWING FR 607 HOUGANG AVE 4 TO PLSC USING KING DOLLEY								140.00 ✓

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMX9556Z

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **49316**
Reg No/Reg Date **SMX9556Z / 22/11/2018**
Date In/Mileage **SMX9556Z / 0**
Chassis No **WDD2130422A455744**
Engine No **27492031479139**
Make/Model **MB/MB E 200 SEDAN AVANTGARDE/AVANTGARDE**
Colour/Trim **028 890 Cavansite B/ 042 215 Leather Mac**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	05/04/2021/ 11:17	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WO: 185188				
M REAR W/SCREEN	1.00	1508.32	00.00	1508.32
M ONE-COMPONENT ADHESIVE	2.00	160.11	00.00	320.22
M BOOT LID MERCEDES STAR	1.00	53.06	00.00	53.06
M GROMMET	3.00	2.64	00.00	7.92
M BOOT LID CHROME MOULDING	1.00	146.33	00.00	146.33
M BOOT LID E200 MODEL PLATE	1.00	93.61	00.00	93.61
M REAR HAT TRAY TRIM	1.00	1831.40	00.00	1831.40
M REAR W/SCREEN ROLLER BLIND	1.00	3109.74	00.00	3109.74
M HOLE PLUG	1.00	9.02	00.00	9.02
M LOCK NUT	1.00	4.21	00.00	4.21
M LOCK NUT	1.00	4.21	00.00	4.21
M RIVET	4.00	3.99	00.00	15.96
M 3RD STOP LAMP	1.00	384.38	00.00	384.38
M 3RD STOP LAMP MOUNTING	1.00	150.24	00.00	150.24
M LEFT REAR TRIM, C-PILLAR	1.00	228.10	00.00	228.10
M RIGHT REAR TRIM, C-PILLAR	1.00	228.10	00.00	228.10
M REAR SEAT BACKREST LEATHER UPHOLSTERY	1.00	3334.44	00.00	3334.44
M REAR SEAT LH/RH HEAD RESTRAINT	2.00	533.10	00.00	1066.20
M REAR SEAT CTR HEAD RESTRAINT	1.00	533.10	00.00	533.10
M HEADLINER	1.00	1754.19	00.00	1754.19

Steve (LKK) 00-AL AL
7/4/21, 12:00 PM EXCER -?
P/P
M Bel Shy
10 dys

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
Authorized signatory and company stamp

Nett **26,482.75**
7% GST on **26482.75** **1853.79**
Total Payable 28,336.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg