



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Ref: CC4/ASM21004405/Bps3q2 Date: 20/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBT 2239L	Veh. Inspected	SLT 646P	
Policy No.	GA565461/1	Coverage (\$)	0.00	
Claim No.	S1M037C8	Excess (\$)	0.00	
Assign From		Assign Date	07/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TUCSON DCT	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHJ3812VJU587740	Colour	WHITE	
Odometer	36512 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	YOKOHAMA	6 mm	
L/H Front Tyre	235/50 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	235/50 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	235/50 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/04/2021	Inspection Date	07/04/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	