

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SLT 646 P**
Model : Hyundai Tucson
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,828.60	\$ 1,828.60 ²⁰¹⁷ 1,828.60
2	Tailgate logo	1	\$ 78.00	\$ 78.00 ^{46.90} 78.00
3	Tailgate emblem 'TUCSON'	1	\$ 89.00	\$ 89.00 ^{43.60} 89.00
4	Tailgate emblem 'TURBO'	1	\$ 75.00	\$ 75.00 ^{57.00} 75.00
5	Tailgate inner trim board	1	\$ 366.50	\$ 366.50 ^{74.60} 366.50
6	Tailgate inner lock	1	\$ 198.10	\$ 198.10 ^{41.08} 198.10
7	Tailgate inner lock sticker	1	\$ 41.08	\$ 41.08 ^{159.00} 41.08
8	Tailgate weatherstrip	1	\$ 245.00	\$ 245.00 ^{202.00} 245.00
9	Tailgate outer garnish	1	\$ 202.00	\$ 202.00 ^{117.40} 202.00
10	Tailgate outer chrome moulding	1	\$ 117.40	\$ 117.40 ^{128.00} 117.40
11	Tailgate windscreen moulding	1	\$ 198.00	\$ 198.00 ^{446.00} 198.00
12	Rear bumper	1	\$ 894.00	\$ 894.00 ^{358.50} 894.00
13	Rear bumper lower	1	\$ 420.00	\$ 420.00 ^{185.90} 420.00
14	Rear bumper outer top garnish	1	\$ 185.90	\$ 185.90 ^{25.00} 185.90
15	Rear bumper side retainer	2	\$ 89.00	\$ 178.00 ^{118.00} 178.00
16	Rear bumper inner sponge	1	\$ 118.00	\$ 118.00 ^{359.90} 118.00
17	Rear bumper reinforcement	1	\$ 359.90	\$ 359.90 ^{38.00} 359.90
18	Rear bumper bracket	2	\$ 68.00	\$ 136.00 ^{76.00} 136.00
19	Rear bumper tow cap	1	\$ 84.00	\$ 84.00 ^{25.00} 84.00
20	Rear bumper reflector	2	\$ 146.70	\$ 293.40 ^{128.00} 293.40
21	Rear bumper reverse sensor	2	\$ 280.00	\$ 560.00 ^{160.00} 560.00
22	Rear end panel	1	\$ 985.60	\$ 985.60 ^{117.80} 985.60
23	Rear end panel top garnish	1	\$ 117.80	\$ 117.80
			Parts Sub Total :	\$ 8,331.28
			20% Discount	\$ 1,666.26
			PARTS TOTAL :	\$ 6,665.02

DD ✓
NECV
NDX
DD ✓
NDX
TN ✓
BR ✓
NNX
NECV
BR ✓
NDX
NECV
NSX
BR ✓
NECV
DLV
BR ✓
SCV
DDX R
NDX

@ 2070
3544.50
708.20
2835.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 100.00
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 50.00
4	Tailgate outer garnish clips	1	\$ 50.00	\$ 50.00
5	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00
6	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00
7	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
8	Rear bumper clips	1	\$ 50.00	\$ 50.00
9	Rear bumper lower clips	1	\$ 50.00	\$ 50.00
10	Rear bumper outer top garnish clips	1	\$ 50.00	\$ 50.00
11	Rear bumper reverse sensor seal	2	\$ 48.00	\$ 96.00
12	Rear end panel sealant	1	\$ 100.00	\$ 100.00
13	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
14	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 1,092.00

NNX
NECV
NECV
NECV
NECV
NSX
NNX
NECV
NSX
NSX
NECV
NNX
NNX
BR

326.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 150.00
2	R&R tailgate windscreen	\$ 250.00
3	Check wiring	\$ 100.00
4	Diagnostic reset fault code	\$ 300.00
5	Upholstery	\$ 300.00
6	Panel beating	\$ 1,400.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ 1,400.00
LABOUR TOTAL :		\$ 4,100.00

NNX
NNX
NNX

Survey Resurvey
7/4/2021 8/4/2021
Terrain in Terrain in
1330 hrs 1410 hrs

PARTS TOTAL : \$ 6,665.02
SPECIAL NETT TOTAL : \$ 1,092.00
LABOUR TOTAL : \$ 4,100.00
GRAND TOTAL : \$ 11,857.02

Lump sum repair
Repair days 7

PARTS 2835.60
SN ~~230.00~~ 326.00
LABOUR 1830.00
~~4995.60~~ 4,991.60
~~998.32~~ 998.32
~~3993.28~~ 3993.28

@ 20%

L/S ~~3993.28~~ 4,000.00

Terrain
17/4/2021