

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Togs not received to the received to					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21004406/Aqf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	[Date:	01/06/2021	
			(Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGH 2556A	Veh. Inspected		GBD 7705J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009716/KY	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		07/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JTFAT35YX0K204196	Colour		SILVER	
	Odometer	241614 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	YOKOHAMA		6 mm	
	L/H Front Tyre	195 R15C	YOKOHAMA		6 mm	
	R/H Rear Tyre	155 R12C	YOKOHAMA		6 mm	
	L/H Rear Tyre	155 R12C	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5. General Information						
	Accident Date	06/04/2021	Inspection Date		07/04/2021	
	Survey held at	Survey held at CN MOTORS PTE LTD				
		1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: