

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBK 267R

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT LH FENDER | TO REPAIR SEE LABOUR | 602.40 | - |
| 1 | FRONT LH DOOR | TO REPAIR SEE LABOUR | 953.10 | - |
| 1 | FRONT DOOR PROTECTOR | CUT | 104.30 | 104.30 |
| 1 | REAR LH DOOR PROTECTOR | CUT | 86.80 | 86.80 |
| | LESS 25% DISCOUNT | | -436.65 | -47.78 |
| | | | 1,309.95 | 143.32 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGES RENEW PARTS REPAIR FENDER .INCLUSIVE OF THE REPAIR OF FRONT LH FENDER AND FRONT LH DOOR. | | 480.00 | 300.00 |
| | TO RENEW HEADLAMPS AND CHECK WIRING FUNCTIONS. | NOT NECESSARY | 30.00 | - |
| | TO PUTTY,APPLY PRIMER & SPRAY PAINT THE AFFECTED AREA. | | 1,000.00 | 850.00 |
| | TUFF KOTE. | NOT NECESSARY | 80.00 | - |
| | | | 1,590.00 | 1,150.00 |
| | GRAND TOTAL | | 2,899.95 | 1,293.32 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 1,000.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/AGI21004407/Uqf3n2

CHUA KANG SENG

Licensed Appraiser