

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Apr 2021 18:59	Clm Veh Model Changed	(204184) TOYOTA DYNA 150 D 3.0 D (M).	[R] Eng Kwok Long
2	06 Apr 2021 18:59	Clm Created	Reg No: GBF6171U. Policy No: DMCVSNW00003852103. Acct Date: 2021/04/01. Claim Type: OD. Insurer: C hina Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Goldbell Engineering Pte Ltd (Tuas). Created from SAS:SG0F21460003	[R] Eng Kwok Long
3	06 Apr 2021 19:08	Clm Submitted	44216.72.	[R] Eng Kwok Long
4	07 Apr 2021 10:17	Clm Registration Modified	Excess: -> 500.00.	[I] Tan Kah Leong
5	07 Apr 2021 10:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):No outstanding premium. Excess \$500 (No waiver). Assigned Appraisals Associates to conduct investigation.	[I] Tan Kah Leong
6	07 Apr 2021 10:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/04/16	[I] Tan Kah Leong
7	07 Apr 2021 10:17	Adj Mandate Set	Approved:0.00.	[I] Tan Kah Leong
8	07 Apr 2021 11:53	Assignment 1st Accessed		[A] LEE SU THING
9	07 Apr 2021 13:03	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] LEE SU THING
10	09 Apr 2021 16:39	Adj Rpt Initiated		[A] SHIAU CHAN
11	09 Apr 2021 17:47	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/04/16	[A] SHIAU CHAN
12	09 Apr 2021 17:47	Adj Mandate Request	Cur Req:43227.92:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER ABLE TO REPAIR THE VEHICLE AT REPAIR COST NOT MORE THAN \$29,000.00 ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	13 Apr 2021 12:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/04/16	[I] Chee So Chow
14	13 Apr 2021 12:19	Adj Mandate Set	Approved:29000.00.	[I] Chee So Chow

Date From
 Date To
 Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2683958	06 Apr 2021 18:59:12	OD/TP Case (Repairer)	Motor	Goldbell Engineering Pte Ltd (Tuas)	Goldbell Engineering Pte Ltd (Tuas)	GBF6171U		xx.xx
2684944	09 Apr 2021 16:39:38	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBF6171U		11.00

